

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

FEB 13 2015

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

*NAB1504750925* OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Wild Cap State Com #5H	Facility Type: Wellhead

Surface Owner: State	Mineral Owner: State	API No. 30-015-37144
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	36	19S	31E	330	North	2260	West	Eddy

Latitude 32.6233208635271 Longitude -103.823902727635

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 30 bbls oil	Volume Recovered: 25 bbls oil
Source of Release: wellhead	Date and Hour of Occurrence: 1-29-2015 7:00 am	Date and Hour of Discovery: 1-29-2015 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <del>Tomas Oberding</del> NMOCD <i>Bratker / Patterson</i>	
By Whom? Amanda Trujillo	Date and Hour: 1/30/2015 5:52 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused when a pulling unit crew left a hold down pin loose in the wellhead and it caused a blowout. Crews reinstalled the pin and was able to stop the blow out.

Describe Area Affected and Cleanup Action Taken.\*

The affected was the pad and the pasture to the southwest and northeast corner of the pad. The impact was a light mist. Crews scraped the pad and microblazed the pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>H...</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>2/10/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>atrujillo@concho.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: February 13, 2015 Phone: 575-748-6940	SUBMIT REMEDIATION PROPOSAL NO	

\* Attach Additional Sheets If Necessary

LATER THAN: *3/10/15*

*2PP-2811*