

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

FEB 11 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

Name of Company: COG Operating LLC		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address: 600 West Illinois Avenue, Midland TX 79701		Contact: Robert McNeill		
Facility Name: Graham Cracker 16 State #2H		Telephone No. 432-230-0077		
		Facility Type: Battery		
Surface Owner: State		Mineral Owner:	API No. 30-015-41533	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	16	26S	28E	190'	North	2080'	West	Eddy

Latitude 32.0492429586896 Longitude -104.094294931342

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 10 bbls Oil ; 50 bbls PW	Volume Recovered: 9 bbls Oil ; 49 bbls PW
Source of Release: Pneumatic dump valve	Date and Hour of Occurrence: 1/24/2015 1:30 PM	Date and Hour of Discovery: 1/24/2015 1:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 1/29/2015 5:11pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a hole in a pneumatic dump valve and occurred within a lined facility. Vacuum trucks were dispatched to recover all standing fluids.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. All fluids were recovered and the facility was put back into production.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 2/12/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: February 11, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-2807