	•		
Submit I Copy To Appropriate District	State of New Me	xico	Form C-103
Office <u>District 1</u> – (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-015-21448
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87		STATE STATE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Sainta Fe, INM 67	505	6. State Oil & Gas Lease No.
87505		**	K-1020
· · · · · · · ·		JG BACK TO A	7. Lease Name or Unit Agreement Name ARTESIA STATE UNIT
· · · · ·	Gas Well 🔲 Other		8. Well Number 901
2. Name of Operator			9. OGRID Number
Alamo Permian Resources. LLC			274841
3. Address of Operator			10. Pool name or Wildcat
415 W. Wall Street, Suite 500, Mic	lland, TX 79701		Artesia; Queen-Grayburg-San Andres
4. Well Location			
	feet from the N line and 1310	) feet from the	E line
Section 23			NMPM County EDDY
Section 25	Township 18S Range 11. Elevation (Show whether DR,		
	11. Elevation (Snow whether DR,	<i>KKD</i> , <i>KT</i> , <i>GK</i> , <i>etc.</i>	
12. Check Ap	propriate Box to Indicate Na	ture of Notice, F	Report or Other Data
		·	-
NOTICE OF INT			SEQUENT REPORT OF:
		REMEDIAL WOR	
		COMMENCE DRI	
	MULTIPLE COMPL	CASING/CEMEN	Т ЈОВ 🗌
OTHER:		OTHER: Clean O	ut, Add Perfs & Acidize
		$\boxtimes$	
<ol> <li>Describe proposed or complet of starting any proposed work proposed completion or recom</li> </ol>	). SEE RULE 19.15.7.14 NMAC.	ertinent details, and For Multiple Com	give pertinent dates, including estimated date pletions: Attach wellbore diagram of
			NM OIL CONSERVATION
			ARTESIA DISTRICT
ee Attached			JAN <b>2 0 2015</b>
		· .	
			RECEIVED
hereby certify that the information abo			
$C_{-}$	ROA TITLE Regul		
IGNATURE $\checkmark$ $\land$ $\land$ $\checkmark$	TITLE Regul	atory Affairs Coor	dinator DATE 1/17/201

	Nu Auc		Regulatory Allan's Coo		ATE_1 <u>11/2019</u> _
Type or print name	<u>CARIESTOKER</u>	E-mail address: ca	arie@stokeroilfield.com	PHONE:	432.897.0673
APPROVED BY:	Filade	TITLE	Dist Taken	3	DATE 44/15
Conditions of Approva	al (if any):				/

/	ARTESIA STATE UNIT #901 (for	merly #001D)
		Perfs: 1460 - 1891' OA
API: 30-015-21448	Lease: K-1020	Spud: 02/10/75
A-23-18S-27E	10 FNL & 1310 FEL	P&A: n/a
Eddy Co., NM	Pool: 3230 - ARTESIA;Queen-Grayburg-SA	

**OBJECTIVE:** Clean out, add perfs, acidize.

<u>12/17/14</u>

MIRU PU. Unhang well & unseat pump. POOH w/pump & rods. ND WH, NU BOP. Unset TAC & tag bottom. LD tag joint. SWI. SDFN.

# 12/18/14

POOH with:

52 jts 2-3/8" J-55 tbg – 12 jts light pitting; 40 jts fair condition 4-1/2" TAC 8 jts 2-3/8" J55 tubing – light pitting 2-3/8" Endurance Jt – good condition Slotted sub – replaced seating nipple PB MH with bull plug (76) ¾" good rods Shop pump

RIH w/3-7/8" used bit & 4-1/2" rotating csg scraper to 1978'. Brk circ & wash dwn to 1985'. Circ well clean. Recovered sand, salt, & paraffin (100 BFW). POOH w/bit & scraper. SWI. SDFN.

## <u>12/19/14</u>

MIRU Wireline Co. (BWWCO) to run GRN/CCL logs from 1976' (wireline depth) up to 291'. First logging tool did not work. POOH & run different logging tool; worked ok. RD WL. Secure well. SDFWE.

## <u>12/20-21/14</u> SDFWE.

#### 12/22/14

MI & set pipe racks. Off-loaded 72 jts 2-3/8" L-80 tbg & tally. MIRU Empire Tubing Testers. PU & tested 62 jts 2-3/8" WS. RD Empire. POOH w/2-3/8" WS. SWI. SDFN.

<u>12/23/14</u>

Perforated Grayburg – Metex, 2 SPF, 19 grain charges as follows:

1906'-1908'

1891'-1895'

1885'-1888'

1856'-1860'

1841'-1844' 1825'-1833'

1814'-1822'

Perforated Grayburg and Upper Grayburg, 2SPF, 19 19 grain charges as follows:

1796'-1799'

1782'-1786'

Perforated QN-LOCO HILLS SS, 2SPF, 19 grain charges as follows:

1706'-1728'

Perforated QN-PENROSE SS, 2SPF, 19 grain charges as follows:

1454'-1471'

Total 11 perforating runs.

All shots fired. Gas increase after perforating. RD Wireline.

SD for Christmas holidays.

Note: 77' and 154 new perfs.

	ARTESIA STATE UNIT #901	formerly #001D)
		Perfs:
API: 30-015-21448	Lease: K-1020	Spud: 02/10/75
A-23-18S-27E	10 FNL & 1310 FEL	P&A: n/a
Eddy Co., NM	Pool: 3230 - ARTESIA;Queen-Grayburg-SA	

#### 01/07/15

MIRU Tubing Testers. PU & RIH w/2-3/8" production BHA testing to 5000 PSI below the slips. Replaced 4 bad jts w/tbg from Alamo pipe yard. Tested ok. RD Empire. ND BOP, NU WH. Noticed excess movement from wellhead. Dug around WH & found crack above bradenhead. Stabilized WH w/gravel & 6 sx of Quickcrete. Secure well. SDFN f/cement to set up.

	Description			Depth
		КВ	6.00'	6.00'
	43	jts 2 <sup>3</sup> / <sub>8</sub> " J55 EUE 8rd Tubing	1369.82'	1375.82'
	1	4½"x2¾" TAC	2.90'	1378.72'
Tubing	16	jts 2 <sup>3</sup> / <sub>8</sub> " J55 EUE 8rd Tubing	513.38'	1892.21'
	1	2 <sup>3</sup> / <sub>8</sub> " Endurance Joint	32.50*	1924.60'
	1	2 <sup>3</sup> / <sub>8</sub> " Seating Nipple	1.10'	1925.70'
	1	2 <sup>3</sup> / <sub>8</sub> " Slotted Sub	6.00'	1931.70'
	1	2-3/8" Mud Anchor w/BP	31.20'	1962.90'

## 01/08/15

No SI well pressure. Set TAC & pulled 10,000 lbs tension. Wellhead would not hold weight (trying to break off). Reset TAC w/5,000 lbs tension. No change. Still would not hold tubing weight. Unset TAC & POOH w/tubing BHA. RIH w/1 jt tbg w/Arrow-set 1X packer. Set pkr & secured well. Prep for backhoe & welder. SDFN.

## 01/09/15

Dug around WH to approx. 5.00' below GL. Cut off 3.00' of surface csg & bradenhead. Cut off bad 4-1/2" csg & weld slip collar on 4-1/2" csg. Replaced rotted 4-1/2" WH with one from Alamo pipe yard. Test csg for leaks, ok. Back-fill hole. RD welder & released equipment. RIH w/2-3/8" production tbg & BHA. Prep for rods. SWI. SDFWE.

	Description			Depth
		KB	6.00'	6.00'
	43	jts 2 <sup>3</sup> / <sub>8</sub> " J55 EUE 8rd Tubing	1369.82'	1375.82'
60	1	4½"x2¾" TAC	2.90'	1378.72'
ing	16	jts 2 <sup>3</sup> / <sub>8</sub> " J55 EUE 8rd Tubing	513.38'	1892.21'
Tub	1	2 <sup>3</sup> / <sub>8</sub> " Endurance Joint	32.50'	1924.60'
	1	2 <sup>3</sup> / <sub>8</sub> " Seating Nipple	1.10'	1925.70'
	1	2 <sup>3</sup> / <sub>8</sub> " Slotted Sub	6.00'	1931.70'
	1	2-3/8" Mud Anchor w/BP	31.20'	1962.90'

#### 01/12/15

SICP 40 psi. PU pump & RIH w/rods. Spaced out well. HWO. Load & test pump to 500 psi, ok. clean location. Load & move WS. RDMO.

}

	Descr	iption	Length
	1	1-1/4"x16.00' Polish Rod w/1-1/2" Liner	16.00'
s	3	<sup>3</sup> / <sub>4</sub> " Pony Rods, 1 ea: 4', 6', 6'	16.00'
tod	75	<sup>3</sup> / <sub>4</sub> " KD Rods	1875.00'
Ľ	1	1.00'x3/4" Lift Sub	1.00'
	1	20-150-12' RWBC Pump	12.00'