

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

FEB 19 2015

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1505530090

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street		Telephone No. 575-748-1471
Facility Name Louise AYI #1		Facility Type Battery

Surface Owner Fee	Mineral Owner Fee	API No. 30-015-31625
----------------------	----------------------	-------------------------

LOCATION OF RELEASE

Unit Letter I	Section 25	Township 21S	Range 26E	Feet from the 1859	North/South Line South	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.44817 Longitude 104.23931

NATURE OF RELEASE

Type of Release Condensate	Volume of Release 18 B/C	Volume Recovered 17 B/C
Source of Release Production Tank	Date and Hour of Occurrence 2/4/2015; AM	Date and Hour of Discovery 2/4/2015; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour 2/5/2015; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The production tank had a gasket leak, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 20' X 40'. Problems with the gasket were corrected and a vacuum truck recovered 94% of the released fluid (17 B/C). Impacted gravel (to include the remaining 1 B/C not vacuumed up) was excavated /hauled to a NMOCD approved facility. Depth to Ground Water: <50' (approximately 20', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20. Based on 94% of the released condensate recovered and all problems with the gasket resolved, Yates Petroleum Corporation requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By:  Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Supervisor	Approval Date: 2/23/15	Expiration Date: N/A
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: February 19, 2015	Phone: 575-748-4217	2RP-

\* Attach Additional Sheets If Necessary

2RP-2831