Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Date 01/10/2015

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMLC064023 6. If Indian, Allottee of	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agre	ement, Name and/or No.	
Type of Well					8. Well Name and No. SAUNDERS 10		
Name of Operator ALAMO PERMIAN RESOURCE	9. API Well No. 30-015-21924-00-S2)0-S2 .			
3a. Address 415 WEST WALL STREET SU MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-897-0673			10. Field and Pool, or RED LAKE	Exploratory		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish,	and State	
Sec 13 T17S R27E NESE 198			,	EDDY COUNT	Y, NM		
12. CHECK APPR	OPRIATE BOX(ES) TO) INDICATE 1	NATURE OF	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent ☑ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans	☐ Fracti	☐ Fracture Treat		plete	☐ Water Shut-Off ☐ Well Integrity ☐ Other	
Tillal Abalidolillielit Notice	☐ Convert to Injection			☐ Water I	rarily Abandon Disposal		
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi	ally or recomplete horizontally, k will be performed or provide operations. If the operation re- andonment Notices shall be fil-	give subsurface lo the Bond No. on sults in a multiple	ocations and measi file with BLM/BI/ completion or rec	ured and true vo A. Required su ompletion in a	ertical depths of all perting bsequent reports shall be new interval, a Form 316	nent markers and zones. filed within 30 days 50-4 shall be filed once	
7/25/2013	•						
Initial reclamation complete (see attached); site ready for inspection NM OIL CONSERVATION ARTESIA DISTRICT							
AN 2/16/15						5	
	XCMIN	n record D		a de la companya de l	RECEIVED		
14. I hereby certify that the foregoing is true and correct. Electronic Submission #215290 verified by the BLM Well Information System For ALAMO PERMIAN RESOURCES LLC, sent to the Carlsbad Committed to AFMSS for processing by KURT SIMMONS on 08/07/2013 (13KMS6935SE)							
Name (Printed/Typed) CARIE ST	OKER		Title REGUL	LATORY AF	FAIRS COORDINA	TOR	
Signature (Electronic S	Submission)		Date 07/30/2	2013			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

JAMES A AMOS TitleSUPERVISORY PET

Office Carlsbad

SITE RESTORATION FORM

Page 1 of 2

OPERATOR: Saunders 10 (P&A)

LAT/LONG: 32.83220 104.22600

FACILITY NAME: Saunders 10 (P&A)

API 30-0-15-21924

LOCATION: Section 13, T 175, R27E

Eddy County, NM, Unit I

Inspections: 7-25-2013

1.) Federal X 2.) State	
1.) Federal X 2.) State	
1.) Federal X 2.) State	
B.) Type Surface	
1.) Native soil X loose soil with gypsum on the surface	
2.) Caliche X	
3.) other	
C.) Well Site Misc.	
1.) Steel marker X	
a. At least, 4" in diameter & 4' above ground X	
b. Set in concrete X	•
c. Info welded or permenantly stamped on marker X	
2.) Electrical Pole X	
3.) Anchors X	
7.) others	
D.) Equipment Onsite	
1.) Sign - H2S, etc X	
2.) Pipelines X	
3.) Flowlines X	
4.) Tanks/Vessels etc. X	
5.) Abandoned lines, type X	
6.) Non-retrieved flowlines/pipelines - fluids removed	
7.) other	
E.)Onsite Debri	
1.) Trash/Junk etc.	
2.) Cement/Concrete or bases X	
3.) Metals etc. X	
4.) Other	
F.) Surface Staining	
1.) Asphaltic soil X	
2.) Salts X	
3.) Oily soils X	
4.) Stressed Areas	
5.) Other:	
G.) Reserve Pit Area	\$1.22 s
1.) Pit present site X Not Present	
2.) Pit vegetation %	
3.) Barren Areas around pit	
4.) Plastic Liner Evidence in pit	
5.) Surface Salt Staining	
6.) Runoff or Erosional Issues	
7.) Other	

SITE RESTORATION FORM

Page __2_ of __2__

OPERATOR: Alamo

FACILITY NAME: Saunders 10

INSPECTION CHECKLIST	YES	NO	REMARKS				
H.) Location and Access Road		A A A					
1.) Is the access road used by other entities		Х.					
2.) If the road is not used by other entities:							
a. locaton & access road ripped & fenced off			Road ripped and seeded 7-25-2013				
3.) Other roads							
I.) Site Reclamation							
1.) Location Leveled	х						
2.) Location Ripped/Disked	×		Pad Ripped and Seeded 7-25-2013				
3.) Erosional Issues - on and off pad site	х						
4.) Erosional Controls - on and off pad site	х		Diversion installed 7-25-2013 to prevent drainage from				
4.) Area fenced	х						
5.) Seeded and % Growth							
4.) other							
Comments:							
			•				
			· · · · · · · · · · · · · · · · · · ·				
		,					
			•				
Work to be performed for closure	100	Tanggan.	CANDARCOT DECEMBER AND ASSESSED ASSESSED BY A SECTION OF A				
work to be performed for closure							
		•					
<u> </u>							