Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

CD	Artesia
	MI CONC

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.

NMNM025527A

SUNDKY N	OTICES AND REPORTS ON WELLS
Do not use this	form for proposals to drill or to re-enter an
	Use form 3160-3 (APD) for such proposals.

	IO HOLO AND INCH			I			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agree	ment, Name and/or No.	
1. Type of Well					8. Well Name and No. BERRY A 11		
Oil Well Gas Well Oth	· · · · · · · · · · · · · · · · · · ·	CARIE STOK			9. API Well No.		
2. Name of Operator ALAMO PERMIAN RESOURCE	CES LLCE-Mail: carie@sto	CARIE STOK keroilfield.com	EK		30-015-00498-00)-S1	
3a. Address 415 WEST WALL STREET SUITE 500 MIDLAND, TX 79701 3b. Phone No. (include area code) Ph: 432-897-0673)	10. Field and Pool, or Exploratory RED LAKE		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State		
Sec 24 T17S R27E NESW 1650FSL 2310FWL					EDDY COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) T	O INDICATE	NATURE OF	NOTICE, RE	PORT, OR OTHER	DATA	
TYPE OF SUBMISSION			ТҮРЕ О	F ACTION			
	☐ Acidize	☐ Deep	en	☐ Production	on (Start/Resume)	☐ Water Shut-Off	
☐ Notice of Intent	☐ Alter Casing	•	ure Treat	□ Reclama	tion	☐ Well Integrity	
Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recompl	ete	Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon	☐ Tempora	rily Abandon		
				☐ Water Di	isposal	,	
13. Describe Proposed or Completed Op- If the proposal is to deepen direction: Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f	ally or recomplete horizontally rk will be performed or provid l operations. If the operation re bandonment Notices shall be fi	, give subsurface lethe Bond No. on esults in a multiple	ocations and measi file with BLM/BIA completion or rec	ured and true ver A. Required subsompletion in a ne	tical depths of all pertine sequent reports shall be- ew interval, a Form 3160	ent markers and zones. Tiled within 30 days 0-4 shall be filed once	
7/25/2013		•					
Subsequent reclamation requ	ired per BLM complete (s	see attached);	site ready for in	spection			
·		Accepted NMC	IO/D KA 19COID XXD				
14. I hereby certify that the foregoing is	Electronic Submission : For ALAMO PER	MIAN RESOUR	CES LLC, sent 1	to the Carlsba	d [*]		
Name (Printed/Typed) CARIE ST	ommitted to AFMSS for processing by KURT SIMMONS on 08/07/2013 (13KMS6936SE) STOKER Title REGULATORY AFFAIRS COORDINATOR					OR	
,						***	
Signature (Electronic	Submission)		Date 07/30/2	2013			
	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE US	SE		
Annroyed By ACCEPT	ED		JAMES A _{Title} SUPERV			Date 01/10/2015	

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office Carlsbad

SITE RESTORATION FORM

Page 1 of 2

OPERATOR: Alamo Permian Resources

LAT/LONG: 32.81683 104.233269

FACILITY NAME: Berry A #11 (P&A)

LOCATION: Sec 24, T12S, R27E

API- 30 15 8498

Eddy Co. NM, Unit B

		Inspected: 5-8-13 / 7-25-13
YES	NO	The Annual Control of
х		
х		Some dense on surface
	•	
x	, ,	
+ F*,	8 . 7	[1] [2] [2] [2] [2] [3] [3] [4] [4] [4] [4] [4] [4] [4] [4] [4] [4
х		
Χ.		
Х		
Х		·
	х	,
	х	Removed in July
- 12. gr		
	х	
	×	
	х .	
1	×	
1		
	x	
1 30 48 1		
	х	
	Х	Broken up into small pieces with bulldozer tracks.
	х	,
100		
	х	Broken up into small pieces with bulldozer tracks.
	×	
	х	
	х	Could not locate
		·
	X	X X X X X X X X X X X X X

SITE RESTORATION FORM

Page __2_ of __2_

OPERATOR: Alamo

FACILITY NAME: Berry A #11

INSPECTION CHECKLIST	YES	NO.	REMARKS			
H.) Location and Access Road						
1.) Is the access road used by other entities		Х				
2.) If the road is not used by other entities:						
a. locaton & access road ripped & fenced off		х	Needs to be ripped and acess fenced			
3.) Other roads		Х				
I.) Site Reclamation						
1.) Location Leveled	<u> </u>	Х	Slight location slope to the east			
2.) Location Ripped/Disked		Х				
3.) Erosional Issues - on and off pad site		х				
4.) Erosional Controls - on and off pad site		Х				
4.) Area fenced	х		Fenced around well head			
5.) Seeded and % Growth	Х		Seeded 7-25-2013			
4.) other			·			
Comments:						
Some asphaltic soil located west of the well location ne	ear the B	erry A #3	3 Tank Battery . Broken up 7-24-2013			
This area will be included in the reclamation						
Work to be performed for closure	Transfer A					
1.) Remove 2 anchors - Done 7-24-2013	L. (STEWEL, SE)	N1. 401) 1441 (pt	- 19 - 19 - 19 - 19 - 19 - 19 - 19 - 19			
2.) Rip areas - Done 7-24-2013						
1						
		· ··				