

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

FEB 27 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB1506156322* OPERATOR  Initial Report  Final Report

Name of Company: COG Operating LLC *229137* Contact: Robert McNeill  
Address: 600 West Illinois Avenue, Midland TX 79701 Telephone No. 432-230-0077  
Facility Name: Loco Hills 33 #6 SWD Facility Type: SWD Battery

Surface Owner: Federal Mineral Owner: API No. 30-015-37478

**LOCATION OF RELEASE**

*30-015-39478*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	33	17S	30E	2210'	North	2145'	East	Eddy

Latitude 32.7922202589621 Longitude -103.975401459275

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 2246 bbls PW	Volume Recovered: 2210 bbls PW
Source of Release: Piping	Date and Hour of Occurrence: 2/7/2015 11:30 am	Date and Hour of Discovery: 2/7/2015 8:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jeff Robertson - BLM	
By Whom? Lupe Carrasco	Date and Hour: 2/8/2015 11:12 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
This spill was caused fiberglass piping. Vacuum trucks were dispatched to recover standing fluid and dispose of at an NMOCD approved facility. Fiberglass was replaced with poly piping.

Describe Area Affected and Cleanup Action Taken.\*  
The release occurred inside a lined facility, however approximately 36 bbls carried over the dike on to the location and into the pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <i>3/2/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: February 27, 2015 Phone: 575-748-6940	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: *4/2/15*

*2RP. 2844*