

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

MAR 19 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

**OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. **260737** Contact: Tony Savoie  
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 575-887-7329  
Facility Name: PLU-301H Facility Type: Exploration and Production

Surface Owner: Federal Mineral Owner: Federal API No. 30-015-36924

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	27	24S	30E	2460	North	2310	West	Eddy

Latitude N 32.189307 Longitude W 103.870133

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 13 Bbls crude oil and 13 Bbls PW	Volume Recovered: 3 Bbls crude oil and 2 Bbls PW
Source of Release: Stuffing box	Date and Hour of Occurrence: 3/16/15 time unknown	Date and Hour of Discovery: 3/16/15 at approximately 4:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD and BLM	
By Whom? Brad Blevins	Date and Hour: 3/16/15 at approx. 5:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The stuffing box packing failed, the E-pot designed to shut down the well and control fluids failed to operate properly. The well was shut in. Repair crews re-aligned the well and replaced the stuffing box on 3/17/15.

Describe Area Affected and Cleanup Action Taken.\*

The release impacted approximately 9,537 of caliche well pad with standing puddles and flow paths. It also misted approximately 15,000 sq.ft. of pad and approximately 9,000 sq.ft. of pasture area with a light mist. Crews washed down the rig and all of the free standing fluid was recovered. EPI remediation crew responded on 3/17/15. The saturated soil was scraped up, 20 cubic yards of soil was hauled to Lea Lands

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie		Approved by Environmental Specialist <u>Signed By: [Signature]</u>	
Title: Waste Management and Remediation Specialist		Approval Date: <u>3/20/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>tasavoie@basspet.com</u>		Conditions of Approval:	
Date: <u>3/19/15</u> Phone: 432-556-8730		Attached <input type="checkbox"/>	

Remediation per O.C.D. Rules & Guidelines  
SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 4/20/15

\* Attach Additional Sheets If Necessary

2RP.2900