

# NM OIL CONSERVATION

ARTESIA DISTRICT

MAR 26 2015

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
Submit to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

0AB1508554476 229137 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: RJ Unit 129	Facility Type: Wellhead

Surface Owner: Federal	Mineral Owner:	API No. 30-015-03780
------------------------	----------------	----------------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	35	17S	29E	1980'	North	1980'	West	Eddy

Latitude 32.7928243621668 Longitude -104.047528594664

## NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 3 bbls Oil ; 10 bbls PW	Volume Recovered: 0 bbls Oil ; 0 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 3/5/2015 11:00 am	Date and Hour of Discovery: 3/5/2015 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A driver from Richard's Energy Compression Services drove over the line causing the line to break. A backhoe was on site and able to isolate the impacted area quickly.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area was approximately 10' x 300' in the roadway. The backhoe scraped up the impacted soil and hauled to an NMOCD approved facility. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>A. Trujillo</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Signed By <u>Mike L...</u> Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <u>3/26/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>atrujillo@concho.com</u>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: March 25, 2015 Phone: 575-748-6940	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: 4/26/15

2RP-2919