

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESIA DISTRICT

MAR 27 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1500037020

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation	Contact: Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name: State SWD # 3	Facility Type: Injection Well

Surface Owner State	Mineral Owner	API No. 30-015-38978
---------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter E	Section 30	Township 17S	Range 31E	Feet from the 2300	North/South Line FNL	Feet from the 725	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude N32.806401 Longitude W103.914498

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 300 barrels of produced water	Volume Recovered: 260 barrels of produced water
Source of Release: steel discharge line	Date and Hour of Occurrence: 3/4/2015	Date and Hour of Discovery: 3/4/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (NMOCD)	
By Whom? Bruce Baker	Date and Hour: 3/4/2015	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The line was isolated and vacuum trucks were dispatched to pick up standing fluid.

Describe Area Affected and Cleanup Action Taken.*

Approximately 44,000 square feet with 20,000 square feet in pasture. The pasture has been delineated and the majority of the pasture has been excavated to a depth of 1 foot.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Bruce Baker		OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker		Approved by Environmental Specialist: 	
Title: Environmental Technician		Approval Date: 3/31/15	Expiration Date: N/A
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/27/2015	Phone: (432) 631-6982	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 4/3/15

2RP-2923

* Attach Additional Sheets If Necessary