

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating	Contact: Jose Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name: Skelly 401	Facility Type: Oil Well

Surface Owner Federal	Mineral Owner: Federal	Lease No. 3001529817
-----------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 28	Township 17S	Range 31E	Feet from the 1300	North/South Line North	Feet from the 60	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	---------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Oil Produced Water	Volume of Release: 6bbls/1bbls	Volume Recovered: 4bbls/0
Source of Release: 3" Polly line	Date and Hour of Occurrence: 12/23/13 9am	Date and Hour of Discovery: 12/23/13 9:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher NM OCD Terry Gregston-BLM	
By Whom? Gary Wink	Date and Hour: 01/04/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

RECEIVED



NOV 08 2013

NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*

The area was excavated down to 4' BGS and random samples of the contaminated area were taken to the laboratory and analysis was given to Mike Burton of BLM for backfilling approvals. The contaminated soil was hauled off to a disposal approved facility and the areas were backfilled using clean material

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: E. L. GONZALES	Approved by District Supervisor: 	
Title: Field Supt.	Approval Date: 3/20/15	Expiration Date: N/A
E-mail Address: E.L.GONZALES@LINNENERGY.COM	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 4-7-2015	Phone: 505-504-8002	

* Attach Additional Sheets If Necessary

28P-1580