

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: Chevron	Contact: Bradley Blevins
Address: 1616 West Bender	Telephone No.: (575) 391-1462 Ext. 86424
Facility Name: Lotos 15 Federal #1	Facility Type: Oil well

Surface Owner: BLM	Mineral Owner:	API: 30-015-36064
--------------------	----------------	-------------------

**LOCATION OF RELEASE**

Unit Letter P	Section 15	Township 24S	Range 31E	Feet from the 330	North/South Line South	Feet from the 330	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

**Latitude:** N 32° 12' 39.68" **Longitude:** W 103° 45' 29.61"

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release: 9 bbls	Volume Recovered: 0 bbls
Source of Release: Water hauler dumped produced water on pad	Date and Hour of Occurrence: 10/22/13 @ 12:30pm	Date and Hour of Discovery: 10/22/13 @ 12:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Bradley Blevins	Date and Hour: 10/22/13	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

Depth to Water. ~360 ft bgs


If a Watercourse was Impacted, Describe Fully.\* Not Applicable

Describe Cause of Problem and Remedial Action Taken.\* Approximately 9 bbls of produced water were released when a water hauler released its load on the well pad. There was no volume recovered. No remedial work has yet commenced on the location.

Describe Area Affected and Cleanup Action Taken.\* Approximately 2,500 square feet of surface area was impacted by the release. No volume of water was recovered from the site. Soil samples were collected from release area and submitted to Cardinal Laboratories for testing. Having received acceptable results and NMOCD approval, the site has been closed with no further action required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:	Approved by District Supervisor: 	
Printed Name: Bradley Blevins	Approval Date: 9/8/15	Expiration Date: N/A
Title: HE Specialist	Conditions of Approval: Final	
E-mail Address: <a href="mailto:bradley.blevins@chevron.com">bradley.blevins@chevron.com</a>	Attached <input type="checkbox"/>	
Date:	Phone: (575) 391-1462 Ext. 86424	

\* Attach Additional Sheets If Necessary

228-2046