District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

				ν.	aina i	·C, INIVI 0/L	703					
			Rel	ease Notifi	catio	n and Co	orrective A	ction	1			
NAB1510656362						OPERATOR						
Name of Company Apache Corporation \$73						Contact Natalie Gladden						
Address PO Box 1849 Eunice NM 88231						Telephone No. 575-390-4186						
Facility Name Geronimo 28 State #1						Facility Type Production well						
Surface Owner Unknown Mineral Owner						St API No. 30-015-31829						
L				IOC	TIO	NOFDE	FASE	<del></del>	<del></del> _			
						N OF RELEASE  1/South Line   Feet from the   East/West Line   County						
1,	J 28 17S 28E 1500 FS					SL 1800 FE			Los			
[ ·	1 28	1/3	·	<del></del>	FSL		<del></del>	FEL		Lea		
LatitudeLongitude												
NATURE OF RELEASE  Type of Release Produced Water Volume of Release 5 Volume Recovered 0												
Type of Rele	ase Produc	Volume of Release 5			Volume Recovered 0							
Source of Release Water line						Date and H 8/24/11	our of Occurrence	Date and Hour of Discovery 8/24/11 12pm				
Was Immedia	ite Notice C		·	Lat. Elat. n		If YES, To	Whom?	<del></del>	<del></del>	·· <del>···········</del>		<del></del>
			Yes 🔀	No Not Re	quired	D . 111				<del></del>		<del></del>
By Whom? Was a Watero	Dog Poss	Date and Hour  If YES, Volume Impacting the Watercourse.										
was a water	ourse Reac	11 1 E3, VOI	idille mipacting ti	ne water	rcourse.	•						
If a Watercour		Dogaril	- Eville *			<del></del>		<del> </del>				
l la watercour	ise was mip	bacted, Descri	oc runy.									
ŕ												
							į					
Describe Caus	e of Problem	m and Remed	al Action	Taken *								
Describe Cause of Problem and Remedial Action Taken.*  Waterline leak between the Red Lake Battery and the Geronimo well. Line was repaired and remediation began.												
						•		Ü				
Describe Area	Affected ar	nd Cleanup Ac	tion Take	n.*		<del></del>	· · · · · · · · · · · · · · · · · · ·				<del></del>	
				 MOCD Guideline	es.					•		.
I hereby certify	that the inf	formation give	n above is	s true and comple	te to the	best of my kr	nowledge and und	derstand	that pursu	ant to NMO0	CD rul	es and
regulations all	operators ar	e required to r	eport and	or file certain rela	ease not	tifications and	perform correcti	ve actior	ns for relea	ses which m	ay end	langer
public health or	r the enviror	nment. The ac	ceptance	of a C-141 report ivestigate and rem	by the	NMOCD mark	ked as "Final Rep	ort" doe	s not reliev	ve the operati	or of l	iability
or the environm	erations nav ient. In add	ition NMOC	oquatery ii Dacceptai	nce of a C-141 rep	ort doe	contammation es not relieve t	that pose a inrea	t to grou enoneihi	ing water, s lity for con	surrace water	, num	an health
federal, state, or							no operator of rec	ponsion	inty for con	iphanee with	any	, tilei
	\	/	~ 1				OIL CONSI	ERVA	TION D	IVISION		
Signature:√	hh	1000 (-	- VC	add on					, /			}
Signature.	- HANG	ant	/ 1		٦	onroyed by En	uiranmantal Sma	.i1: /	1 /			
Printed Name:	Natalie Glad	dden				proved by En	vironmental Spec	cialist:	no.			
Title: EHS Env	ironmental '	Tech			Ar	proval Date:	411615	Ext	oiration Da	te: NIA		
				,						<del></del>		
3-mail Address:	natalie.gla	dden@yahoo.	com		Co	nditions of Ap	proval: r O.C.D. Rule	s & G	uldeline	Attached [	3	
)ate: 8/26/11	Р	'hone: <i>575-</i> 39	0-4186		SUB	MIT REME	DIATION PRO	POSA	L NO		-	
ttach Addition			3 1100			R THAN:_		<u> </u>	-	1)-	)) <	20-0
		·								<u>L</u> K	29-2	4458