<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

No.

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

Form C-141 Revised October 10, 2003

DEC 1 4 2012

Submit 2 Copies to appropriate

District Office in accordance

NMOCD ARTESIA

Wised October 10, 2003

Copies to appropriate

District Office in accordance
with Rule 116 on back
side of form

side of form

## **Release Notification and Corrective Action**

·			OPERATOR ☐ Initial Report ☐ I					Final Repor					
Name of Comp			Contact Natalie Gladden										
Address P.O. Facility Name		Telephone No. (575) 390-4186  Facility Type Production Well											
Surface Owner Unknown Mineral Owner						BLM API No. 30-015-36638							
						N OF REI	LEASE						
Unit Letter Se	nit Letter Section Township Range Feet from the Nort			North	South Line Feet from the		East/West Line		County				
B 21 17S 30E 900 FNL					FNL		1650	FEL Eddy					
			Lati	tude		Longitude							
NATURE OF RELEASE  Type of Release Brine Water Volume of Release 30 bbls Volume Recovered 0 bbls													
Type of Release	Volume of Release 30 bbls Volume Recovered 0 bbls												
Source of Release Workover/flowback						Date and Hour of Occurrence Date ar				Hour of Discovery			
Was Immediate	If YES, To Whom?												
By Whom? Note													
By Whom? Natalie Gladden  Was a Watercourse Reached?  ☐ Yes ☒ No						Date and Hour 11/17/11 858 am If YES, Volume Impacting the Watercourse.							
If a Watercourse	was Imp	acted, Descri	be Fully.*			··l·····	<del></del>						
Describe Cause o	f Proble	m and Remed	dial Action	Taken.*				<del>.</del>					
Describe Cause of Problem and Remedial Action Taken.*  While doing a workover procedure to fish out stuck rods and tubing the well flowed back.													
		*											
7	PC . 1	161		<u>.</u>		<del> </del>	·•						
Describe Area Af The leak affected					area of	pasture land	including a right-	of-wav	for a high r	oressure gas	nipelin	e. Impacted	
The leak affected the caliche pad surrounding the well head and an area of pasture land including a right-of-way for a high pressure gas pipeline. Impacted soils were removed to a NMOCD approved disposal facility. Soil samples were collected from the excavations and sent to a commercial laboratory for													
confirmation of c	confirmation of chloride and TPH. The excavations were backfilled with clean caliche and topsoil and contoured to the surrounding area.												
I hereby certify th	at the in	formation giv	ven above	s true and compl	ete to th	ne best of my	knowledge and ur	iderstar	d that purs	uant to NMC	CD ru	les and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
or the environmer federal, state, or le				ince of a C-141 r	eport do	oes not relieve	the operator of re	esponsi	bility for co	mpliance wi	ith any	other	
	OIL CONSERVATION DIVISION												
Signature: Thus Toward I													
						Approved by District Supervisor:							
Printed Name: N		11/1/1/2010											
Title: EH&S Environmental Tech						Approval Date: 4/16/15 Expiration Date: 1/1/							
E-mail Address: 1	Conditions of Approval:												
Date: 11912 Phone: (575) 390-4186						Attached  Attached							
Attach Additiona	l Sheets	s If Necessa	ry							2RP-	- 113	3/)	