


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Nagooltee Peak 5 Com #2	Facility Type	Production
Surface Owner	Mineral Owner	Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	5	22S	24E					Eddy County, NM

Latitude N 32.42393 Longitude W 104.5245

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	90 bbls	Volume Recovered	75 bbls
Source of Release	Flow line corrosion/flow line	Date and Hour of Occurrence	5/29/12	Date and Hour of Discovery	5/29/12
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD, Jennifer VanCuren-BLM		
By Whom?	Christopher Jones	Date and Hour	6/1/12 @ 7:24 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Corrosion in a flow line caused 90 bbls of produced water to spill onto the ground. 75 bbls of water were recovered via vacuum truck.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 12' x 405'. Corrosion in a flow line caused 90 bbls of produced water to spill onto the ground. 75 bbls of water were recovered via vacuum truck. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 11/14/2012 and James Amos of the BLM via email on 03/12/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:		
Printed Name: Christopher Jones	Approval Date: 6/21/15 Expiration Date: N/A		
Title: HES Specialist	Conditions of Approval: Final Attached <input type="checkbox"/>		
E-mail Address: Christopher.Jones@oxy.com			
Date: 5/29/13 Phone: (575) 628-4121			

* Attach Additional Sheets If Necessary

22P-1170