## **NM OIL CONSERVATION**

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

\* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources APR 2 0 2015

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

2RP- 2965

RECEIVED

Santa Fe, NM 87505

1220 S. St. Francis Dr., Santa Fe, NM 87505 **Release Notification and Corrective Action OPERATOR** ☐ Initial Report Final Report Name of Company Devon Energy Production Contact Rudy Zuniga, Production Foreman Address 6488 Seven Rivers Hwy Artesia, NM 88220 **Telephone No.** 575-390-5435 Facility Name TNT 6 Fed Com 1 Facility Type Gas Surface Owner Federal Mineral Owner Federal API No. 30-015-31712 LOCATION OF RELEASE Unit Letter Section Township Feet from the North/South Line Feet from the East/West Line Range County 17S 29E 660' **FSL** 1980' Eddy O 6 **FEL** Latitude: Longitude: NATURE OF RELEASE Type of Release Oil & Produced Water Spill Volume of Release .5bbls Volume Recovered Obbls Source of Release Flowline **Date and Hour of Occurrence Date and Hour of Discovery** April 16, 2015 10:30 AM April 16, 2015 10:30 AM Was Immediate Notice Given? If YES, To Whom? Jeff Robertson, BLM Mike Bratcher, OCD By Whom? Date and Hour Jeff Robertson, BLM April 16, 2015 12:30 PM Ray Carter Mike Bratcher, OCD April 16, 2015 12:35 PM Was a Watercourse Reached? If YES, Volume Impacting the Watercourse ☐ Yes ☒ No N/A If a Watercourse was Impacted, Describe Fully.\* N/A Describe Cause of Problem and Remedial Action Taken.\* On April 16, 2014 at 10:30 AM fluid was noticed misting out of the flow line in the vicinity of the TNT 6 Fed Com 1, upon arrival it was discovered that the flow line possibly had a weak spot which resulted in a 3 inch by 1.5 inch slit that released an estimated .5bbl of mixed oil and produced water into pasture. Describe Area Affected and Cleanup Action Taken.\* The affected area is approximately a 100x100 area in the pasture located northwest of the lease road leaving the TNT 6 Fed Com 1. Obbls were recovered and the area will be raked and the surrounding vegetation will be pressure washed with Dawn soap. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Sheila Fisher Printed Name: Sheila Fisher Approved by Environmental Specialist: Approval Date: Title: Field Admin Support **Expiration Date:** E-mail Address: Sheila.Fisher@dvn.com Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached Date: 4/20/15 Phone: 575.748.1829 SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 6/24/15