

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 30 2014

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

1 MLR 1405827737

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Cedar Canyon 28 Federal #4 SWD Battery	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No. 30-015-29118 (nearest well)	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	28	24S	29E					Eddy County, NM

Latitude N 32.18643° Longitude W 103.99157°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	10 bbls oil and 20 bbls produced water	Volume Recovered	29 bbls
Source of Release	High skim tank level causes fluid to go out skim tank line	Date and Hour of Occurrence	01/28/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen- BLM		
By Whom?	Kathy Purvis	Date and Hour	01/29/2014 @ 2:34 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

High skim tank level causes 10 bbls of oil and 20 bbls of produced water to leak onto the ground. 29 bbls of fluid were recovered via vacuum truck and the problem was corrected.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 30' x 30' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Chancey Summers

Title: HES Specialist

E-mail Address: Chancey.Summers@oxy.com

Date: 1-30-14 Phone: (575) 397-8216

OIL CONSERVATION DIVISION

Approved By: 
Signed By: Mike Bratcher
Approved by Environmental Specialist:

Approval Date: FEB 27 2014

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:
3/26/14

Attached ☐

* Attach Additional Sheets If Necessary

2RP-2179