

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

APR 29 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB 1512156316		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: OXY USA INC		Contact: Chris Jones			
Address: 102 S. Main St. Carlsbad, NM 88220		Telephone No.: 575-628-4121			
Facility Name: Two Marks 36 State #4 SWD		Facility Type: SWD			
Surface Owner: State		Mineral Owner:		API No.: 30-015-34833	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	36	21S	24E	670'	South	1905'	East	Eddy

Latitude 32.430102 N Longitude -103.454029 W

NATURE OF RELEASE


Type of Release: Produced Water	Volume of Release: 10 bbls	Volume Recovered: 0 bbls
Source of Release: 4" Steel Line Leak	Date and Hour of Occurrence 3/30/2015	Date and Hour of Discovery 3/30/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken: A 4" steel salt water disposal line caused a 10 barrel release on location due to stress on the line. All fluids stayed on location.

Describe Area Affected and Cleanup Action Taken.* ☐ The impacted area was on location only measuring approximately 60' x 80'. Talon/LPE was contracted to perform initial site assessment and soil sampling activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com , c=US Date: 2015.04.28 15:48:06 +05'00'</small>	OIL CONSERVATION DIVISION	
Printed Name: Chris Jones	Approved by Environmental Specialist: 	
Title: HES Specialist	Approval Date: 4/11/15	Expiration Date: N/A
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval:	
Date: 4/28/2015 Phone: 575-628-4121	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 4/11/15	

* Attach Additional Sheets If Necessary

Attached ☐

2RP-2977