

NM OIL CONSERVATION

ARTESIA DISTRICT

MAY 05 2015

Form C-141

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name XTO ENERGY INC.	Contact Sherry Pack
Address 200 N. LORAIN, STE. 800	Telephone No. 432.620.6709
Facility Name Nash 42	Facility Type Battery

Surface Owner XTO ENERGY INC.	Mineral Owner XTO ENERGY INC.	API No. 30-D15-21277
---	---	--------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	13	23S	29E	1980	N	660	E	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Flaring	Volume of Release 5200 mcf/d	Volume Recovered
Source of Release casinghead gas	Date and Hour of Occurrence 5/4/15 12:00 pm	Date and Hour of Discovery 5/5/15 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson	
By Whom? Patty Urias	Date and Hour 5/5/15 10:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully. *

Describe Cause of Problem and Remedial Action Taken. *

Enterprise compressor issues causing us to flare approx. 5200mcf/d as of 12:00 pm 5/4/15.

Describe Area Affected and Cleanup Action Taken. *

Flaring is being used to minimize emissions

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.

Signature: <i>Patty Urias</i>	OIL CONSERVATION DIVISION	
Printed Name: Patty	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory Analyst	Approval Date: 5/4/15	Expiration Date:
E-mail Address: patty_urias@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/5/2015	Phone: 432.620.4318	Remediation per O.C.D. Rules & Guidelines

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: **6/12/15** **2RP2962**