

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company - OXY USA	Contact - Kelton Beaird
Address - P O Box 1988 / Carlsbad, NM	Telephone No. - 575-628-4121
Facility Name - Roaring Springs 14 Fed Com #1	Facility Type - Battery

Surface Owner - Federal	Mineral Owner - Federal	Lease No.
-------------------------	-------------------------	-----------

LOCATION OF RELEASE

Unit Letter E	Section 14	Township 21S	Range 23E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE




Type of Release - Produced Water	Volume of Release - +500 bbls	Volume Recovered - 480 bbls
Source of Release - Discharge Line	Date and Hour of Occurrence 10-22-08	Date and Hour of Discovery - 10-22-08 @ 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Sherry Bohnam - NMOCD Jim Amos - BLM	
By Whom? - Kelton Beaird - Oxy	Date and Hour - Same as above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.* Victalic clamp on the water pump discharge line broke, filling the battery with water. Spill was contained within the berms. All fluid was picked up with a vacuum truck. The battery will be delineated using field analysis. Confirmation samples will be taken to the lab. The groundwater in the surrounding area is > 98' using a borehole drilled at the nearby Roaring Springs 13 Fed #4 Battery. The borehole was in Section 13 T21S R23E. The following are the recommended action levels for the site : Chloride - 500 ppm, TPH - 1,000 ppm, BTEX - 100 ppm(field vapor analysis).

Describe Area Affected and Cleanup Action Taken.* As per the approved plan the impacted soil at SB1 and SB2 was to excavated 1' bgs and SB3 was 5' bgs. Very hard rock was encountered at 3' 6" at SB3 and a confirmation sample was taken. As per the conversation with Mike Bratcher the soil below 3' 6" at SB3 would be left in place due to the hard rock. 150 cubic yards of impacted soil was removed from the pile and the remaining impacted soil was blended with clean caliche to below the RAL's and backfilled into the excavation. The berms around the battery were rebuilt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Kelton Beaird		Approved by District Supervisor: 	
Title: HES Specialist		Approval Date: 4/27/15	Expiration Date: N/A
E-mail Address: kelton_beaird@oxy.com		Conditions of Approval: 	
Date: 8-31-09		Attached <input type="checkbox"/>	
Phone: 575-628-4121			

* Attach Additional Sheets If Necessary

22P-263