District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

					OPERA	ГOR	☐ Initial Report ☐ Final Report							
Name of Co	mpany	Oxy Permiar			Contact Dusty Wilson				·- · · · ·		·			
Address 1017 W. Stanolind Rd, Hobbs, NM						Telephone No. (575) 397-8247								
Facility Name Federal 26 #3						Facility Type Production								
Surface Owner BLM Mineral Owner						BLM			Lease No. 30-015-26788					
			LO	CATION OF	REL	EASE A	PI #30_015_2	28305						
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the		Vest Line	County				
C	26	22S	31E							Eddy				
			La	titude		_ Longitud	le							
				NAT	URE	OF REL	EASE				•			
Type of Rele	ase Oil an	d Produced v		Volume of Release 15 bo & 5 bw V				Volume Recovered none						
Source of Re	lease Liner	Seperated			Date and I 07/30/201	Hour of Occurrence	Date and Hour of Discovery 07/30/2011							
Was Immedia	nte Notice C				If YES, To Whom?									
	•		Yes	No 🛛 Not Re	equired	d n/a								
By Whom?					Date and Hour n/a									
Was a Water	course Read		1		If YES, Volume Impacting the Water									
			No		N/A				RECEIVED					
If a Watercou	ırse was Im	pacted, Descri	*						JAN 11 2012					
									Ĺ	NMOCE	AR	TESIA		
Describe Cause of Problem and Remedial Action Taken.* Liner broker inside well head. No free liquids could be recovered. Remediation complete as described in the OCD and BLM approved remediation plans.														
Describe Are	Describe Area Affected and Cleanup Action Taken.*													
The liner inside the well head broker causing the release of oil and produced water to leak into location area. Cleanup was performed by excavating the impacted area and backfilling the site with clean soil. Confirmation sampling was performed and the results were provided to the BLM and NMOCD. Remediation approvals were provided by the OCD on 10/12/2011 and by the BLM on 10/24/2011.														
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.														
	1	1 4		OIL CONSERVATION DIVISION										
Printed Name: Dusty L. Wilson						Approved by District Supervisor:								
	Specialist		Approval Date: 4/24/15 Expiration Date: NA											
E-mail Addre		/_Wilson@o	xy.com			Conditions o			7	Attached				
Date: 1-4-1				575-397-8210				17/	ul_					
Attach Addi	ional Shee	ets If Necess	ary							2RP-	883			