

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

SEP - 2 2009

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company OXY USA	Contact Kelton Beard
Address 102 S Main Carlsbad, NM 88220	Telephone No. (O) 505-887-8337 C) 575-390-1903
Facility Name Mckittrick Hill CTB	Facility Type Tank Battery

Surface Owner BLM	Mineral Owner BLM	Lease No.
-------------------	-------------------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	14	22S	24E					Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Oil	Volume of Release 132.48	Volume Recovered
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery

Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD Jim Amos-BLM
--	---

By Whom? Rick Kerby	Date and Hour 1:40pm 5-1-2008
---------------------	-------------------------------



Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.
---	---

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Hole in the bottom of the tank allowed fluid to leak out on the ground. All fluid contained inside secondary containment

Describe Area Affected and Cleanup Action Taken.\*  
Due to hard rock, the area was excavated to a depth of 15 inches. According to the Water map the groundwater is >100' bgs. At a depth of 5' samples were taken and were below the acceptable levels.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Kelton Beard	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 5/4/05	Expiration Date: N/A
E-mail Address: kelton_beard@oxy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date:		

\* Attach Additional Sheets If Necessary

Some contamination in place  
work done as agreed upon  
by OCP/BLM

2RP-163