

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1515334420 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company Cimaxex Energy 1621083	Contact Gloria Garza
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-234-3204
Facility Name: Wersell Federal 1	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner	API No. 30-015-20915
------------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 04	Township 22S	Range 27E	Feet from the 810	North/South Line FNL	Feet from the 1980	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.42693 Longitude: -104.19662

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 20 BBLS	Volume Recovered: 0 BBLS
Source of Release: Flow line	Date and Hour of Occurrence: 5/28/2015	Date and Hour of Discovery 5/28/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson BLM & Mike Bratcher OCD	NM OIL CONSERVATION
By Whom? Gloria Garza	Date and Hour: 6/1/2015 4:20 PM CST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	ARTESIA DISTRICT JUN 1 2015

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

Corrosion on a 45 pipe fitting attaching two flow lines. Moving forward we will fuse the two flow lines together to eliminate fitting washing out.

Describe Area Affected and Cleanup Action Taken.*

Talon Environmental Services will remediate the impacted soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gloria Garza</i>	OIL CONSERVATION DIVISION	
Printed Name: Gloria Garza	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: ESH Tech	Approval Date: 6/2/15	Expiration Date: N/A
E-mail Address: ggarza@cimaxex.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: 6/2/2015 Phone: 432-234-3204	Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

ATER THAN: **6/2/15**

2RP-3027