

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

HMP

Release Notification and Corrective Action

Accepted as Initial
ONLY

☒ Initial Report ☒ Final Report

NAB1515240134

OPERATOR

Name of Company	Devon Energy Production	Contact	Mike McMahan
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575.706.4165
Facility Name	Dickens 29 Fed 3 Battery	Facility Type	Oil

Surface Owner Federal	Mineral Owner Federal	API No.	30-015-37220
-----------------------	-----------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	29	16S	28E	2310	FNL	330	FEL	EDDY

Latitude: 32.89405

Longitude: 104.19059

NATURE OF RELEASE

Type of Release Spill	Produced Water	Volume of Release	5 BBL	Volume Recovered	4 BBL
Source of Release	Water haulers back valve	Date and Hour of Occurrence	2.18.15 at 12:45 PM	Date and Hour of Discovery	2.18.15 at 12:45 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM & OCD			
By Whom?	Mike McMahan	Date and Hour	2.18.15 BLM at 6:05 PM / 2.18.15 OCD 6:10 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse		ARTESIA DISTRICT	

BLM OIL CONSERVATION

MAY 13 2015

NM OIL CONSERVATION
ARTESIA DISTRICT
MAY 13 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Driver was loading off of the produced water tank and did not realize the back valve on the trailer was opened.
The hauler shut off the pump and the open valve and called a supervisor.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

Fuson did one call and did cleanup work. They back dragged area where spray occurred on location. Roustabout rerouted line to prevent upward spray.

Analytical Data Required HMP

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Jeanette Barron	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist:	HMP
Title: Field Admin Support	Approval Date: 6/11/15	Expiration Date: N/A
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5.13.15 Phone: 575.748.1813	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 6/2/15

2RP-3026