

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION  
ARTESIA DISTRICT  
JUN 8 2015 AB  
RECEIVED Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

NAB1516026655

303900 OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Memorial Production Operating LLC	Contact Heather Dolphin
Address 500 Dallas Street Houston TX 77002	Telephone No. 832-797-1334
Facility Name Loco Hills A Federal #002	Facility Type Well

Surface Owner	Mineral Owner	API No. 30-015-20536
---------------	---------------	----------------------

### LOCATION OF RELEASE

Unit Letter N	Section 10	Township 17S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°50'37.00"N Longitude 103°57'43.02"W

### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 20bbls	Volume Recovered 0bbls
Source of Release Well	Date and Hour of Occurrence 6/6/15	Date and Hour of Discovery 11:45pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson, OCD / Jeff Robertson, BLM	
By Whom? Heather Dolphin	Date and Hour 6/8/15 1:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. n/a	

If a Watercourse was Impacted, Describe Fully.\*

n/a



Describe Cause of Problem and Remedial Action Taken.\*

Underground hammer union in Injection line developed a hole underground. The leaking hammer union and one bad joint of pipe was replaced.

Describe Area Affected and Cleanup Action Taken.\*

Off location (lease road & pasture), area approx 10 x 30 with a couple of small 1ft. wide streams going about 50' into the field.  
Waiting on clean-up approval from BLM due to spill being off pad and requiring an endangered species/ archaeological clearance.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Heather Dolphin	Approved by Environmental Specialist: 	
Title: Sr. Regulatory Specialist	Approval Date: 6/8/15	Expiration Date: N/A
E-mail Address: heather.dolphin@memorialrd.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/8/15	Phone: 832-797-1334	Remediation per O.C.D. Rules & Guidelines

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 7/2/15

2RP-3040