

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1516757810

OPERATOR <input checked="" type="checkbox"/> Initial Report <input checked="" type="checkbox"/> Final Report	
Name of Company Devon Energy Production <i>U137</i>	Contact Rudy Zuniga, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-390-5435
Facility Name Aquila 22 Fed Com 1H	Facility Type Oil
Surface Owner Federal	Mineral Owner Federal
API No. 30-015-40627	

LOCATION OF RELEASE

Unit Letter A	Section 22	Township 19S	Range 31E	Feet from the 990	North/South Line FNL	Feet from the 50	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	---------------------	-----------------------	----------------

Latitude: 32.6505145262188

Longitude: -103.848726636463

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 10bbbls	Volume Recovered 10bbbls
Source of Release 3" fill line to produced water tank	Date and Hour of Occurrence July 11, 2015 10:50 AM	Date and Hour of Discovery July 11, 2015 10:50 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM	
By Whom? Rudy Zuniga, Production Foreman	Date and Hour July 11, 2015 12:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 15 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

On June 6, 2015 10:50 AM J&J Solutions Contractor called Asst. Foreman Automation who then contacted Asst. Production Foreman and reported a leak at the Aquila 22 Fed Com 1H, upon arrival it was discovered that a 3" fill line to the produced water tank had a hole in it releasing 9.5bbbls produced water and .5bbl oil into lined containment. The affected tank was immediately switched out of and the line was isolated.

Describe Area Affected and Cleanup Action Taken.*

The affected area was a 30x80 area inside the lined containment. All fluids were recovered and containment has no holes. Containment and equipment will be pressure washed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>		OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support		Approval Date: <i>6/16/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: Sheila.Fisher@dyn.com		Conditions of Approval: <i>FINAL</i>	
Date: June 15, 2015 Phone: 575.748.1829		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-3053