

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1518054044 102683

Name of Company Cimax Energy	OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address 600 N Marienfeld Ste 600 Midland TX	Contact Christine Alderman	
Facility Name Gadwall 18 Fed Com 2H	Telephone No. 432-853-7059	
	Facility Type production	
Surface Owner Federal	Mineral Owner	API No. 30-015-39141

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	18	25S	27E	150	N	2310	W	Eddy

Latitude 32.13681 Longitude -104.23044

NATURE OF RELEASE

Type of Release produced water	Volume of Release 30 bbls	Volume Recovered 0
Source of Release poly flowline	Date and Hour of Occurrence 06/25/2015	Date and Hour of Discovery 06/25/2015 5:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Randy Pair	
By Whom? Christine Alderman	Date and Hour 6/26/2015 11:00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 26 2015

Describe Cause of Problem and Remedial Action Taken.\*

Poly flowline ruptured

RECEIVED

Describe Area Affected and Cleanup Action Taken.\*

Release happened on back side of location pad an area approximately 60 yds X 15 yds, and ran 100 yds down cowpath. Diversified will assess and develop workplan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Christine Alderman	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: [Signature]	
Title: ESH Supervisor	Approval Date: 6/29/15	Expiration Date: N/A
E-mail Address: calderman@cimaxex.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: 6/26/2015 Phone: 432-853-7059	LATER THAN: 7/30/15	

\* Attach Additional Sheets If Necessary

2RP-3076