

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NAB1518149184

277558 OPERATOR

☒ Initial Report ☐ Final Report

Name of Company : LIME ROCK RESOURCES II-A, LP	Contact : Mike Barrett
Address : 1111 Bagby Street Suite 4600, Houston, TX 77002	Telephone No. : 575-623-8424
Facility Name: Logan 35 Water Transfer Line	Facility Type: Transfer Line

Surface Owner :	Mineral Owner:	API:30-015-30439
-----------------	----------------	------------------

LOCATION OF RELEASE

Unit Letter N	Section 35	Township 17S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	-------------

Latitude 32.78584 N Longitude -104.25050 W

NATURE OF RELEASE

Type of Release : Mix Fluids	Volume of Release : 350 bbls PW 5 bbls Oil	Volume Recovered: 300 bbls PW 5 bbls Oil ✓ 1 bbl
Source of Release : Downed Power Line	Date and Hour of Occurrence: 6/25/2015 3:30 pm	Date and Hour of Discovery: 6/25/2015 @ 3:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM/Jeffery Robertson & OCD/Mike Bratcher - voicemail	
By Whom? Sheldon Hitchcock with Talon/LPE	Date and Hour :6/25/2015 @ 4:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* ☐ A downed power line ignited causing a fire which melted the flow lines. The facility and wells were shut in. The BLM fire department responded. The lines were cut and capped. A vac truck was immediately called to the site and recovered 300 barrels of produced water and 1 barrel of oil. Talon/LPE was contacted for the emergency response.

Describe Area Affected and Cleanup Action Taken.* ☐ Talon mobilized personnel and equipment for emergency cleanup and sampling.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Michael Barrett</u>	Approved by District Supervisor: <u>[Signature]</u>	
Printed Name: Michael Barrett	Approval Date: <u>6/30/15</u>	Expiration Date: <u>N/A</u>
Title: Production Supervisor	Conditions of Approval:	
E-mail Address: mbarrett@limerockresources.com	Attached <input type="checkbox"/>	
Date: 6/26/2015 Phone: 575-623-8424	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/01/15

2RP-3084

* Attach Additional Sheets If Necessary

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 29 2015

RECEIVED