

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 29 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

0AB1518157994

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: COG Operating LLC 329137		Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077	
Facility Name: Dodd Federal Unit #15A Battery		Facility Type: Battery	
Surface Owner: Federal		Mineral Owner:	API No. 30-015-35139

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	17S	29E	330	South	1040	East	Eddy

Latitude 32.8282736195051 Longitude -104.057446775274

NATURE OF RELEASE

Type of Release: Oil and Water	Volume of Release: 5 bbls oil; 20 bbls PW	Volume Recovered: 4.5 bbls oil; 19.5 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 6/13/2015 8:00 am	Date and Hour of Discovery: 6/13/2015 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM	
By Whom? Amanda Trujillo	Date and Hour: Mon 6/15/2015 5:49 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a tank over flowed due to a water pump failure. Vacuum trucks were dispatched to recover the standing fluid and repairs were made to the pump.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. All fluids were able to be recovered. The facility was cleaned and put back in to service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By:  Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 6/30/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: June 29, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RD-3087