

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**JUN 29 2015**

Form C-141  
Revised August 8, 2011

**RECEIVED** in appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1518152971**

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: COG Operating LLC <b>229137</b>		Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077	
Facility Name: MYOX 32 STATE #001H		Facility Type: Battery	
Surface Owner: State		Mineral Owner: State	API No. 30-015-41641

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	32	25S	28E	190	South	1980	East	Eddy

**Latitude 32.0794496978159 Longitude -104.107254270382**

**NATURE OF RELEASE**



Type of Release: Oil and Produced Water	Volume of Release: 15 bbls Oil; 30 bbls PW	Volume Recovered: 12 bbls oil; 25 bbls PW
Source of Release: Gasket Failure	Date and Hour of Occurrence: 6/12/2015 6:30 am	Date and Hour of Discovery: 6/12/2015 6:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: Mon 6/15/2015 5:03 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused by a gasket failure FWKO. Vacuum trucks were dispatched to recover all standing fluids and repairs were made to the equipment.

Describe Area Affected and Cleanup Action Taken.\*  
This release occurred within a lined facility. All fluids were able to be recovered and the facility put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Signed By  Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <b>6/30/15</b>	Expiration Date: <b>N/A</b>
E-mail Address: atrujillo@concho.com	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: June 29, 2015	Phone: 575-748-6940	

\* Attach Additional Sheets If Necessary

**2RP-3086**