

07/10/2015 18:46

5756279778

OFFICEMAX

PAGE 03/08

RECEIVED 07/06/2015 09:42

5756279778

OFFICEMAX

3172

07/04/2015 08:04

5057489720

OCD ARTESIA

PAGE 01/01

## NM OIL CONSERVATION

District I  
1623 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUL 13 2015

Submit 1 Copy to appropriate District Office in  
accordance with 19.13.29 NMAC.

RECEIVED

## NAB1619053557 Release Notification and Corrective Action

ROGER SLAYTON DBA

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EXCUBILLA OIL #228270	Contact	ERIC SANCHEZ
Address	PO Box 687	Telephone No.	505 840 4234
Facility Name	STANDARD STATE #2	Facility Type	Pump Jack
Surface Owner	State of NM	Mineral Owner	ROGER SLAYTON
		API No.	30-005-10129

STATE

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Foot from the	North/South Line	Foot from the	Edge/West Line	County
B	5	8S	27E					Chaves

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

Type of Release	Flow Line (Livestock)	Volume of Release	2 BBLs	Volume Recovered	2 BBLs 155 Gallons + Recovered
Source of Release	Flow Line	Date and Hour of Occurrence	8-15	Date and Hour of Discovery	8-16-15
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					

NONE

Describe Cause of Problem and Remedial Action Taken.\*

Livestock Stepped on Flow Line

Describe Area Affected and Cleanup Action Taken.\*

20' EAST of Pump Jack  
2 BBLs OIL Carried + spread by Rain Water on Oil Field Road  
We have excavated to clean Soil, Contaminated Soil Stock Piled on Plastic, Hauled to proper Disposal site

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: ROGER SLAYTON	Accepted for record	
Title: OWNER	Approved by Environmental Specialist: NMOC	Approval Date: 7/14/15
E-mail Address:	Expiration Date: N/A	Conditions of Approval:
Date: 7-10-15	Phone: 505 840 5058	Remediation per O.C.D. Rules & Guidelines

\* Attach Additional Sheets if Necessary

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 8/16/15

2RP-3112