

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 08 2015

Form C-141
Revised August 8, 2011

RECEIVED
Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0AB1519556419

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. <u>2100737</u>		Contact: Bradley Blevins	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: PLU CVX JV BS 016H		Facility Type: Exploration and Production	
Surface Owner: Federal		Mineral Owner:	API No. 3001540581

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	25S	30E	200		2130		Eddy

Latitude 32.153395 Longitude 103.867621

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 9 barrels	Volume Recovered: 2 barrels
Source of Release: Corrosion to steel connection	Date and Hour of Occurrence: 6-30-2015 @ 11:00am	Date and Hour of Discovery: 6-30-2015 @ 12:06pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* BOPCO EHS was notified of a release the occurred due to corrosion of a steel connection on the flowline. A vacuum truck was called to the location and recovered 2 barrels of produced water.		
Describe Area Affected and Cleanup Action Taken.* A vacuum truck recovered 2 barrels of produced water.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <u>Bradley Blevins</u>	OIL CONSERVATION DIVISION	
	Signed By <u>Mike Erickson</u>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: <u>7/14/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: bblevins@basspet.com	Conditions of Approval:	
Date: <u>7-8-2015</u> Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/11/15

2RP-3105