

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 14 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

14B1519857428 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 2100737	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit #085 at James Ranch Unit #017 Battery (Battery at JRU #017 well, API 30-015-27784)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Unknown	API No. 30-015-35322
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	6	23S	31E	2180	South	185	West	Eddy

Latitude 32.33553° Longitude -103.81980°

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water	Volume of Release 4 bbls oil, 24 bbls PW	Volume Recovered None
Source of Release Flow Line	Date and Hour of Occurrence 7/10/2015 hour unknown	Date and Hour of Discovery 7/10/2015 at 12 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)	
By Whom? Amy Ruth	Date and Hour 7/10/2015 at 5:36 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Buried steel line weakened by corrosion. Line was clamped until joint of line replaced.

Describe Area Affected and Cleanup Action Taken.*

Leak affected 780 square feet of pasture west of the JRU 17 Battery pad. Leak area was covered with plastic to prevent downward migration until it is addressed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground-water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Signed By  Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 7/17/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 7/14/2015	Phone: 432-661-0571	

SUBMIT REMEDIATION PROPOSAL NO

* Attach Additional Sheets If Necessary

LATER THAN: 8/20/15

2RP-3128