

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

JUL 14 2015

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

**NAB1519 853006**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <b>260737</b>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Big Eddy Unit #164	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-35592
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter J	Section 27	Township 21S	Range 29E	Feet from the 1650	North/South Line South	Feet from the 1650	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.447313° Longitude -104.968975°

**NATURE OF RELEASE**



Type of Release Crude Oil and Produced Water	Volume of Release 1 bbl oil, 6 bbls PW	Volume Recovered 1/2 bbl oil, 2 bbls PW
Source of Release Tank Overflow	Date and Hour of Occurrence 7/5/2015 at 12 am	Date and Hour of Discovery 7/5/2015 at 12 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)	
By Whom? Amy Ruth	Date and Hour 7/5/2015 at 5:09 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

**Describe Cause of Problem and Remedial Action Taken.\***  
BEU 164 well unloaded during the night and tank overflowed into earthen berm containment. Alarm levels were then set during the afternoon on 7/5/2015 to prevent future over flow events.

**Describe Area Affected and Cleanup Action Taken.\***  
Leak affected 305 square feet of caliche pad within the earthen containment. Vac truck recovered standing fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy Ruth	Signed By  Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 7/17/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/14/2015 Phone: 432-661-0571	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO**  
**LATER THAN: 8/20/15**

**2RP-3126**