District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

0.0			Rei	ease moun	catio		orrective A	cuon	
NABIE	52025.	3667			,	<b>OPERA</b>	<b>TOR</b>	🛛 Initi	al Report
Name of Company: BOPCO, L.P.						Contact: Amy Ruth			
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Telephone No. 575-887-7329			
Facility Name: 10" SWD Line located 4,650 ft. S of JF Harrison Federal #1 API 30-015-04749						Facility Type: Exploration and Production			
Surface Owner: Federal Mineral Owne						: Unknown API No. 30-015-04749			
						N OF RE	LEASE	·	
Unit Letter						South Line	Feet from the	East/West Line	County .
D	13	25S	30E	38	North		320	West	Eddy
· ·		<u> </u>	La	<del></del>		Longitude  OF REL	-103.842015°		
							Volume of Release 80 bbls Volume Recovered 30 bbls		
Source of Release 10" SWD line rupture						Date and Hour of Occurrence Date and Hour of Discovery			
Course of North 10 CT D Into Tapitate						Date and hour unknown 7/15/2015 7:45 am			
Was Immedia	ate Notice (					If YES, To Whom?			
☐ Yes ☐ No ☐ Not Required									
By Whom? Amy Ruth						Date and Hour 7/15/2015 2:57 pm  If YES, Volume Impacting the Watercourse.			
Was a Watercourse Reached? ☐ Yes ☒ No						N/A NM OIL CONSERVATION			
If a Watercou	rse was Im	pacted, Descr	ibe Fully.*			· dan			ARTESIA DISTRICT
N/A									JUL 17 2015
	•								- 7 2013
Describe Cau Steel riser des	veloped a h	ole due to inte	rnal corro	sion. The line w	as isolate	ed, drained, a	nd clamped. Line	will be repaired.	RECEIVED
The leak affect	cted 1,015 s	quare feet of	pasture and	i 500 square feet				standing fluids.	
regulations all public health of should their of	operators a or the environerations ha ment. In ac	are required to conment. The live failed to a ldition, NMO	report and acceptance dequately CD accept	I/or file certain r c of a C-141 repo investigate and r	elease no ort by the emediate	tifications an NMOCD ma contamination	d perform correct arked as "Final Re on that pose a thre	ive actions for rele port" does not reli- at to ground water	uant to NMOCD rules and ases which may endanger eve the operator of liability , surface water, human health impliance with any other
Signature: July						OIL CONSERVATION DIVISION			
Printed Name: Amy Ruth						Approved by Environmental Specialist:			
Title: Assist	ant Remedi	ation Forema	n .		^	Approval Date	7/21/15	Expiration [	Pale: NA
E-mail Addres	s: ACRu	th@basspet.co	om	,		Conditions of	Approval:	Rules & Guide	iAaached 🗌
Date: 7/1	7/2015		Phone:	432-661-0571	SI	IBMIT RE	MEDIATION	ROPOSAL N	
Attach Additi	onal Sheet	s If Necessa	ry		LA	TER THA	N: 022	115	2RP-3139