

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1520238826 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Cimarrex Energy <i>102483</i>	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Cottonwood Draw 22 Fed 2H	Facility Type production

Surface Owner BLM	Mineral Owner	API No. 30-015-36757
-------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	22	25S	26E	2310	S	380	E	Eddy

Latitude 32.11436 Longitude -104.272

NATURE OF RELEASE

Type of Release oil/produced water	Volume of Release 12 bbls oil 8 bbls PW	Volume Recovered 4 bbls oil 6 bbls PW
Source of Release gas regulator	Date and Hour of Occurrence 07/09/15	Date and Hour of Discovery 07/09/15
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Randy Pair	
By Whom? Gloria Garza	Date and Hour 07/09/15 10:30 pm	NM OIL CONSERVATION ARTESIA DISTRICT JUL 16 2015
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

The gas regulator on the safety system of the well was installed incorrectly and rather than having a supply of gas it was getting fluids. The regulator failed which failed to shut in the well. This has been corrected.

Describe Area Affected and Cleanup Action Taken.*

Location pad and slightly down a cow path into the pasture area. An environmental company will delineate and develop work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: ESH Supervisor	Approval Date: <i>7/21/15</i>	Expiration Date: <i>NIA</i>
E-mail Address: calderman@cimarrex.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: Phone: 432-853-7059	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>7/22/15</i>	

* Attach Additional Sheets If Necessary

2RP-3136