

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1520255168

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Rudy Zuniga
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-390-5435
Facility Name	Serene Sisters 25 Fed 4	Facility Type	Oil

Surface Owner	State	Mineral Owner	Federal	API No.	30-015-38312
---------------	-------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	25	18S	31E	200	South	1750	West	Eddy

Latitude: N 32°7'10.66"

Longitude: W 103°83'11.82"

NATURE OF RELEASE

Type of Release Spill	Volume of Release	Volume Recovered
PW	6 bbls	0 bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Leak in water line	7/17/2015 @ 10:30 AM	7/17/2015 @ 10:30 AM
Was Immediate Notice Given?	If YES, To Whom?	NM OIL CONSERVATION ARTESIA DISTRICT JUL 17 2015 RECEIVED
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Kellie Jones OCD Jim Amos BLM	
By Whom?	Date and Hour	
Rudy Zuniga	7/17/2015 @ 12:26 PM 7/17/2015 @ 12:30 PM	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

On July 17, 2015 at 10:39 AM Rudy Zuniga Devon Energy Production Foreman received a call from Jim Huerta Devon Energy Assistant Production Foreman notifying him that he received a call from Dwayne Concho Lease Operator that there was a leak by the Serene Sisters 25 Fed 4 Battery. Rudy drove to location and found the leak about 1/4 mile from the battery right next to the lease road into the pasture. From what Rudy observed the hole looked like the line had been shot causing the leak of 6 bbls of produced water.

Describe Area Affected and Cleanup Action Taken.\*

Rudy isolated the line so no more fluid could get out. None of the 6 bbls was recovered. This will have to be assessed for clean up

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Corina Moya	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 7/21/15	Expiration Date: N/A
E-mail Address: corina.moya@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/20/2015 Phone: 575.746.5559	Remediation per O.C.D. Rules & Guidelines	
SUBMIT REMEDIATION PROPOSAL NO		

\* Attach Additional Sheets If Necessary

LATER THAN: 8/22/15

2RP-3141