

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	St Mary Land & Exploration Co.	Contact	Tom Morrow
Address	3300 N. A Street, Bldg. 7, Ste. 200, Midland, TX 79705	Telephone No.	432-688-1773
Facility Name	ESDU Injection Station	Facility Type	Injection Station
Surface Owner	BLM	Mineral Owner	BLM
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	24	18S	31E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	500 bbls	Volume Recovered	410 bbls
Source of Release	Fire destroyed water tanks & gun barrel	Date and Hour of Occurrence	7/16/08 6:00 AM	Date and Hour of Discovery	7/16/08 6:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher w/NMOCD & Jim Amos w/BLM			
By Whom?	Bill Heame	Date and Hour	5/30/2008 10:01 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Cause: Lightning struck injection station burning down (3) 500-bbl fiberglass suction tanks and scorching a 750 bbl fiberglass gun barrel.
Fill lines were broken away from tanks causing the spill.

Remedial Action: Notified all oil companies and shut-in all off lease water entering facility.

Describe Area Affected and Cleanup Action Taken.*

Affected Area: 85' x 45' = 3825 sq. ft. & 100' x 95' = 9500 sq. ft. Total = 13,325 sq. ft. (Pasture Land)

Cleanup Action: Picked up standing fluid w/vacuum truck. Waiting on orders from BLM/OCD for further cleanup remediation action.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dorria Huddleston</i>		OIL CONSERVATION DIVISION	
Printed Name: Dorria Huddleston		Approved by District Supervisor: <i>[Signature]</i>	
Title: Production Tech		Approval Date: 7/20/15	Expiration Date: N/A
E-mail Address: dhuddleston@stmaryland.com		Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 3/27/2009 Phone: 432-688-1789			

* Attach Additional Sheets If Necessary

2RP-208