

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 22 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.  
**RECEIVED**

Release Notification and Corrective Action

NAB1520442349 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production <u>0131</u>	Contact Mike McMahan	
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.706.4165	
Facility Name Riverside 31 Fed Com 1	Facility Type Oil	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-31351

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	31	16S	27E	660	FSL	660	FEL	EDDY

Latitude: 32.873486 Longitude: 104.311043

NATURE OF RELEASE

Type of Release Spill Fire & produced water	Volume of Release 4 BBL	Volume Recovered 0 BBL
Source of Release Lightning strike on fiberglass tank	Date and Hour of Occurrence 7.19.15 at 5:00 pm	Date and Hour of Discovery 7.19.15 at 5:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos - BLM Mike Bratcher - OCD	
By Whom? Mike McMahan	Date and Hour 7.20.15 8:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

7/19/15 on the Riverside 31 Federal Com 1 Battery at 5:30 pm a Lighting Strike on Fiberglass Water Tank. The proper authorities were notified and well was shut in. 4 BBL of produced water was sprayed off pad with nothing recovered.

Describe Area Affected and Cleanup Action Taken.\*

4 BBL of produced water sprayed off the south side of pad a 20 X 10 area nothing was recovered. An environmental group will be call out for evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jeanette Barron</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Jeanette Barron</u>	Signed By <u>Mike Bratcher</u>	
Title: <u>Field Admin Support</u>	Approved by Environmental Specialist:	
E-mail Address: <u>Jeanette.barron@dm.com</u>	Approval Date: <u>7/23/15</u>	Expiration Date: <u>N/A</u>
Date: <u>7.22.15</u> Phone: <u>575.748.1813</u>	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	
		Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

LATER THAN: 8/24/15

2RP-3147