NM OIL CONSERVATION District I State of New Mexico ARTESIA DISTRICT 1625 N. French Dr., Hobbs, NM 88240 Form C-141 **Energy Minerals and Natural Resources** Revised August 8, 2011 District II JUL 2 3 2015 811 S. First St., Artesia, NM 88210 Submit 1 Copy to appropriate District Office in District III **Oil Conservation Division** accordance with 19.15.29 NMAC. 1000 Rio Brazos Road, Aztec, NM 87410 1220 South St. Francis Dr. District IV RECEIVED 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 *REVISION **Release Notification and Corrective Action** NAB/520447244 **OPERATOR** Final Report Initial Report Name of Company Devon Energy Production Contact Mike McMahan Address 6488 Seven Rivers Hwy Artesia, NM 88220 Telephone No. 575.706.4165 Facility Name Riverside 31 Fed Com 1 **Facility Type Oil Mineral Owner Federal** API No. 30-015-31351 **Surface Owner Federal** LOCATION OF RELEASE Unit Letter Section Township Feet from the North/South Line Feet from the East/West Line Range County . Gar ---- 31----16S 27E. 660* FSL STREET 22.47.2. · 660 - FEL ----EDDY Latitude: 32.873486 Longitude: 104.311043 NATURE OF RELEASE Type of Release Spill Fire & produced water Volume Recovered Volume of Release 4 BBL 0 BBL Source of Release Lightning strike on fiberglass tank **Date and Hour of Occurrence Date and Hour of Discovery** 7.19.15 at 5:00 pm 7.19.15 at 5:00 pm Was Immediate Notice Given? If YES, To Whom? Yes 🗋 No 🗋 Not Required Jim Amos - BLM Mike Bratcher - OCD By Whom? Mike McMahan **Date and Hour** 7.20.15 8:00 am Was a Watercourse Reached? If YES, Volume Impacting the Watercourse 🗌 Yes 🛛 No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* 7/19/15 on the Riverside 31 Federal Com 1 Battery at 5:30 pm a Lighting Strike on Fiberglass Water Tank. The proper authorities were notified and well was shut in. 4 BBL of produced water. 3 ½ BBL inside unlined containment and ½ BBL was sprayed off pad with nothing recovered. **Describe Area Affected and Cleanup Action Taken.*** 4 BBL of produced water 3 1/2 BBL inside unlined containment and 1/2 BBL was sprayed off the south side of pad a 20 X 10 area. 3 1/2 BBL was recovered from containment and nothing was recovered of the '/ BBL on pasture. An environmental group will be call out for evaluation. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. **OIL CONSERVATION DIVIS** Signature: Jeanette Barron Signed By Mile Printed Name: Jeanette Barron Approved by Environmental Specialist: fitle: Field Admin Support Approval Date: **Expiration Date:** Conditions of Approval: -mail Address: Jeanette.barron@dvn.com Attached Remediation per O.C.D. Rules & Guidelines ate: 7.22.15 Phone: 575.748.1813 SUBMIT REMEDIATION PROPOSAL NO ttach Additional Sheets If Necessary 2RP-3147 ATER THAN: D