District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

## RECEIVED State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division

FEB -6 2010 1220 South St. Francis Dr. NMOCD ARTESIA Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

## Release Notification and Corrective Action

						OPERA	TOR		Initi	ial Report	$\boxtimes$	Final Repor	
Name of Co	mpany O	XY USA		Contact Ke	lton Beaird								
Address 1502 W. Commerce Carlsbad, NM 88220						Telephone No. (O) 575-628-4100							
Facility Name Indian Basin Station 133						Facility Type Production Facility							
Surface Owner BLM Mineral Owner						Lease No.3001528813							
							EACE		1 20000				
Unit Letter	Section	Township	Range	Feet from the		N OF REI	Feet from the	East/W	est Line	County	•		
Oun Letter	Section	Township	Range	reet nom me	Noru	WSOUGH LINE	reet from the	East W	est Line	County			
F	33	21S	24E					<u> </u>		Eddy			
LatitudeLongitude													
				NAT	URF	OF RELI	EASE						
Type of Release Produced Water							Volume of Release 15bbls   Volume Recovered 4bbls						
Source of Rel							and Hour of Discovery						
Was Immedia	te Notice (	Given?		11-22-09 @ 10:00am   If YES, To Whom?									
was illilicula	iie Nonce C		Yes 🗌	No 🛛 Not Re	quired	11 155, 10 WHOIII:							
By Whom?				Date and Hour See above									
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Waterson	rae was Im												
ii a watercou	If a Watercourse was Impacted, Describe Fully.*												
Describe Caus	Describe Cause of Problem and Remedial Action Taken.*												
	6 inch tubing line rusted, causing the line to split												
Describe Area	Affected a	and Cleanup A	ction Take	en.*				<del></del>		<del></del>			
Area affected	was on the	location aprox	x. 50' X 30	0'. A vac-truck w									
				required levels. G							rotecti	ion and	
surface body o	or water pro	nection. Site	will be left	t as is. Lab analy	iicai is	in the original	remediation plan	i mat was	submitte	u.			
		•••											
I harabu aartif	u that tha is	formation air	ion about	is true and compl	ata ta t	ha haat of must	manuladas and	d o not - m d	th	want to NIMC	CD	1 d	
				is true and comple d/or file certain re									
public health o	r the enviro	onment. The	acceptance	of a C-141 repor	t by the	e NMOCD ma	rked as "Final Re	eport" doe	es not reli	eve the opera	tor of	liability	
should their op	erations ha	ive failed to a	dequately i	investigate and re ance of a C-141 r	mediat	e contaminatio	n that pose a thre	eat to grou	and water	, surface wat	er, hun	nan health	
federal, state, o	nent. In ad or local law	s and/or regul	ations.	ance of a C-141 to	Sport a	oes not reneve	the operator of r	esponsibi	iity for co	impliance wi	in any	otner	
					$\top$		OIL CONS	SERVA	TION	DIVISIO	V		
C:			<i>(</i> )	/	/ /			,	1		<del>-</del>		
Signature:	120				<del>-</del> -				L				
Printed Name:	Kelton Be	aird				Approved by L	istrict Superviso	or: 7	ny	1			
Title: HES Sp	ecialist					Approval Date	7/13/15	- Ex	piration I	Date: 11/	<i>A</i>		
							<del></del>						
E-mail Address	s: kelton_b	eaird@oxy.co	om		'	Conditions of A	Approval:		1	Attached			
Date: 2-2-10							¥	)h	<u> </u>		_		
attach Additional Sheets If Necessary													
										CKIN	12	/	