
| | | . • | | | | | |
|---|---|---|--|----------------------|--|---------------------------------------|--|
| | UNITED STAT DEPARTMENT OF THE BUREAU OF LAND MAN | INTERIOR | FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 | | | | |
| | 5. Lease Serial No. NMLC029395B | | | | | | |
| SUNDR` Do not use t abandoned w | 6. If Indian, Allottee or Tribe Name | | | | | | |
| SUBMIT IN TI | 7. If Unit or CA/Agreement, Name and/or No. | | | | | | |
| 1. Type of Well | | × | , <u> </u> | | 8. Well Name and No. | · · · · · · · · · · · · · · · · · · · | |
| Oil Well 🔲 Gas Well 🔲 G | TURNER B 71 | | | | | | |
| 2. Name of Operator LINN OPERATING INCORF | 9. API Well No. 30-015-05454-00-S1 | | | | | | |
| 3a. Address 600 TRAVIS STREET SUIT HOUSTON, TX 77002 | Field and Pool, or GRAYBURG | Exploratory ' | | | | | |
| 4. Location of Well (Footage, Sec., | T., R., M., or Survey Descripti | on) | <u> </u> | | 11. County or Parish, | and State | |
| Sec 29 T17S R31E SWSW | ` | EDDY COUNTY, NM | | | | | |
| 12. CHECK AP | PROPRIATE BOX(ES) | TO INDICATI | E NATURE OF | NOTICE, RE | PORT, OR OTHE | R DATA | |
| TYPE OF SUBMISSION | 1 | | F ACTION | | | | |
| Notice of Intent | Acidize | 🗖 De | epen ' | D Producti | on (Start/Resume) | U Water Shut-Off | |
| Notice of Intent | Alter Casing | 🗖 Fra | cture Treat | 🗖 Reclama | ition | Well Integrity | |
| Subsequent Report | Casing Repair | 🗖 Ne | w Construction | 🗖 Recomp | mplete Other | | |
| ☐ Final Abandonment Notice | Change Plans | 🗖 Plu | g and Abandon 🛛 🛛 Tempo | | arily Abandon | | |
| , • | Convert to Injectio | n 📋 Plu | g Back | 🗖 Water D | | | |
| determined that the site is ready for LINN respectfully requests a to determine and quantify re project is an extension of the is working towards submittin | one year temporary aba maining potential in the a existing Seven Rivers F | rea. At this tin lood in the are | ne, the most pror a of the subject v | mising vell. LINN | lucted | • | |
| converted to an injector. | | | | | | | |
| | NM | OIL CONS | STRICT | OFF | | | |
| A c c a a 1 a 1 | · · · | JUL 29 | | ÷ | ATTACHED F | | |
| ACCOPTEC NMC | for record | • | | CONI | DITIONS OF | APPROVAL | |
| | 7/30/15 | RECEI | VED | | <u> </u> | | |
| 4. I herebý certify that the foregoing | Electronic Submission For LINN OPER | #287323 verific ATING INCORF | d by the BLM We ORATED, sent to | Il Information | System | | |
| | mmitted to AFMSS for pro A MORENO | | | | ADVISOR FOR N | M | |
| Signature (Electronic | Submission) | · · | Date 01/08/2 | 2015 | | | |
| | THIS SPACE F | OR FEDER | AL OR STATE | OFFICE US | ÈE | | |
| Approved By ame | Q ams | | Title S | PE1 | ······································ | 7.23 . Date | |
| nditions of approval, if any, are attach tify that the applicant holds legal or e new would entrie the applicant to com- | quitable title to those rights in t | | Office | FO | | | |
| tle 18 U.S.C. Section 1001 and Title 4 States any false, fictitious or fraudulen | 3 U.S.C. Section 1212, make it statements or representations | a crime for any p as to any matter w | erson knowingly and vithin its jurisdiction. | l willfully to mal | ke to any department or | agency of the United | |
| ** BLM RE | /ISED ** BLM REVISE | ED ** BLM RI | EVISED ** BLA | | ** BLM REVISE |) ** | |

· · ·

.

•

.



LINN Energy Well Name: TURNER B.71.

www.peloton.com

| 9/UWI 001505454 | | B-GRAYBURG | | N | itate/Prov | 29 0 | ownstup 117-S | Range 031-E | Survey | | ock |
|------------------------------------|---------------------------------------|---------------------|-----------------------|--|---|----------------------------|------------------|---|---|--|---|
| ound Elevation (f) Org 3,692.00 | KB Elev (ft) 3,692.00 | (D-Ord (ft) 0.00 | Initial Soud 9/9/1 | Dato Rig Release Da 1960 | | 0/17/1960 | Lattude (1) | 2° 48' 0.25 | 2"N | | Operated 16" W Yes |
| LALGER MAL | ····· Original H | ole; 1/7/2015 4 | 38:16 P) | Mulationala | in the second | | | Origina | al Hole D | ata: | |
| ND KB), Met Nillee | A STATE AND A V | ert cal schema | lic (aclua | <u>, - casara ing</u> | | /ellbores | ary yr yr yw | alar da da dageten da Ser da gradat da da Manasanah da gerera | ur ar ann an thairt an thairt an tha ann an thairte an tha ann an thairte | | on an |
| ىمانىتىكەسسىيدىشىلىر | | | inistration in the | 8 5/8, Surface, Cas | ing. | orth-South Dist | 1.1 | NS FLA 30.0 FSL | g / East-West | | 2,616.0 FEL |
| 5 P | | | | F10.0-590.0 Wellbore: 10: 0.0-5 | 90.0 | asing Strir | | OD Nom | Nom IWU | on (I] String Gra | de TRun Date |
| 519.2 | | | | Surface Casing Cer | ment; S | urface : sg Cos | 590.0 | 8 5/8 | 8.097 2 | 4.00 J-55 | 9/13/196 |
| 745 | | | 2 | 4 1/2 Production; C | Casing | roduction | 3,672.0 | 4 1/2 | 4.09 | 9.50 J-55 | 10/19/19 |
| 90.≱° | · · · · · · · · · · · · · · · · · · · | | | Wellbore 8 590 0- 3,672 0 | | 1.30 E.10 C | ges (| | Bm (ħKB) | 1997) 1997 - Starley Starley 1997 - Starley St | Com |
| S1 | | | | Retrievable Bridge | | urface Casi roduction C | ng Cement | 0.0 | 590.0 1 3,672.0 1 | 00 sx cmt | |
| 2 holes; 3, | 225.0-3,227.0- | | | 3,175,0-3,180,0,41 | | ement | asing | 3,155.0 | 3,072.0 | 00:5X5 GHT | an an an an State an an |
| | hole: 3,234,0 | | | | | ubing Com | ponents | | D (in) | (in) Wi (ii | b/i) [Length (f |
| 46.1 | | | | | | ubing m Description | | | 2 3/8 | 1.867 (in) W1 (ii | 4 70 3,621 |
| | 246 0-3,248 0- | | | | S | eating Nipp | le | | 2 3/8 | 1,867 | |
| | hole 3,264 0— | | | en e | N | lud Anchor | | | 2 3/8 | (in) 1.867 | b/ft) Length (f 28 |
| | hole, 3,281.0- | | | r de la companya de l Para de la companya d | | ther in Hol | Jetradual Manual |] : 8tm (RK8) | Run Dalo | 1977 (M. 1987) 27 | Com |
| | hole; 3,290.0 | | | | | etrievable ridge Plug | .3,175,0 | 3,180.0 | 1/7/2015 | | ED: Retain for 7 Rivers W |
| | hole: 3,303.0 | | | | | | . [: | L | [| expansion | |
| Parls - ElParts | hole, 3,309.0 | | | | | | | | | | |
| mia: | | | | | | | | . • | | | |
| 2 holes, 3, | 311,0-3,313.0- | | <u> </u> | | | · · · · | | | | | |
| 177.1 | hole: 3,327.0- | | | | : | | | | | | |
| en.9 | hole, 3,361.0— | | | | | · . · . | : . | , | | | |
| 91.1 | hole: 3,391.0— | | | | | | | | | | |
| 65.0 | hole: 3,399.0 | | | | | | | | | · · · · | |
| 1 | hole, 3,424.0 | | | | | ÷ | | • • | | | |
| 923 : 1 | hole: 3,432.0 | | | strandina (Maria) Santa (Maria) | | | | | | | |
| 37.0 D balan D | 27.0.2.420.0 | | | | | · · · | | | | | |
| 2 notes, 3,4 39.0 | 137.0-3.439.0 | | | | | | | | | | · · · |
| 400 1 | hole: 3,440.0, | | | ļ | | | | | | | • • |
| 69.7 44 holes 3.4 | 69.0-3.480.0- | | | у 3 - Л | | | | | | | |
| 810 | | | | k. | | | | | | | |
| 25.0 1 | hole; 3,626.0,—e | | | · | | | | | | | |
| 21.0 1 | hole: 3,628 0 | | | | | | | | | | |
| 29. | hole: 3,630.0 | | | • | | | | | | | |
| n.a 1 | hole, 3,632,0— | | | | | | | | | | |
| | hole: 3,635.0— | N. A. | | | | | | | | • | |
| | hole, 3,637.0- | | 财 | | | | | | , | | |
| | hole; 3,639.0—c | | M | | | | | | | | |
| | hole: 3,641 0 | | | • | | | | | | | |
| 50 | hole: 3,645.0 - | 1.1.1.1 | 1.22 | Weilbore: 3,672.0 | 1 | | | | | | |

NM Regulatory Schematic

. ال Report Printed: 1/7/2015

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).

2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.

2. A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).

2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.

2. A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.