

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1521756095

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Memorial Production Operating LLC	Contact	Heather Dolphin
Address	500 Dallas Street, Suite 1800, Houston, TX 77002	Telephone No.	832-797-1334
Facility Name	KLM Battery	Facility Type	Production

Surface Owner	Mineral Owner	API No.	30-015-04411
---------------	---------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	31	17S	30E					Eddy

Latitude 32°47'28.56"N Longitude 104° 0'44.58"W

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	7bbls Oil 23bbls PW	Volume Recovered	30bbls
Source of Release	Battery	Date and Hour of Occurrence	8/2/15	Date and Hour of Discovery	8/2/15 10am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos, BLM & Heather Patterson, NMOCD		
By Whom?	Heather Dolphin Sr. Regulatory Specialist	Date and Hour	8/2/15 4:17pm	3:17pm	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.*

n/a



Describe Cause of Problem and Remedial Action Taken.*

A valve upstream from the circulating pump washed out and wouldn't hold fluid back. The spill filled up the berm around the circ. Pump and overflowed it.

Describe Area Affected and Cleanup Action Taken.*

100ftx1ft all the way down to the County Road 217 were it puddled 2ft x4ft. Vacuumed up all free standing liquid, then the pumper spread dirt over the spill on the asphalt. Will wait on further instruction from BLM and OCD to give us some direction on how they want this cleaned up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Heather Dolphin	Approved by Environmental Specialist: 	
Title: Sr. Regulatory Specialist	Approval Date: 8/5/15	Expiration Date: N/A
E-mail Address: heather.dolphin@memorialrd.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/3/2015 Phone: 832-797-1334	Mediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/16/15

2RP-3188