

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	St. Mary Land & Exploration Co.	Contact	Donna Huddleston
Address	3300 N. A Street, Bldg. 7, Ste. 200 Midland, Tx	Telephone No.	(432) 688-1789
Facility Name	Parkway Delaware Unit #507	Facility Type	Injection

Surface Owner: BLM	Mineral Owner: BLM	Lease No.
--------------------	--------------------	-----------



#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	35	19S	29E					

Latitude N 32.61698° Longitude W 104.04187°

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 35 bbls	Volume Recovered 8 bbls
Source of Release: Hose connecting injection line to the wellhead.	Date and Hour of Occurrence 12/27/2009	Date and Hour of Discovery 12/27/2009
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher with OCD & Jim Amos with BLM	
By Whom? Bill Hearne	Date and Hour 12/27/2009 1:34 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Found split in 1.0" 4000# WP rubber hose connecting injection lateral line to wellhead for injection. Hose has been replaced. Picked up 8 bbls of produced water.		
Describe Area Affected and Cleanup Action Taken.* Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Aaron Hale agent for Sun Energy		Approved by District Supervisor: 	
Title: Project Manager		Approval Date: 6/29/10	Expiration Date: N/A
E-mail Address: aaron.hale@tetratech.com		Conditions of Approval: Final	Attached <input type="checkbox"/>
Date:	Phone: (432) 682-4559		

\* Attach Additional Sheets If Necessary

2RP-393