

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1522442205

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production	Contact Garry Michael
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-4895
Facility Name Cotton Draw Unit 89	Facility Type SWD

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-31381
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter O	Section 3	Township 25S	Range 31E	Feet from the 250'	North/South Line FSL	Feet from the 1980'	East/West Line FEL	County Eddy
---------------	-----------	--------------	-----------	--------------------	----------------------	---------------------	--------------------	-------------

Latitude: 32.1528893

Longitude: -103.7636414

NATURE OF RELEASE


Type of Release Spill	Volume of Release 35bbl	Volume Recovered 25bbl
Source of Release 4" high pressure hose	Date and Hour of Occurrence August 6, 2015 5:04 PM	Date and Hour of Discovery August 6, 2015 5:04 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM Mike Bratcher, OCD	NM OIL CONSERVATION ARTESIA DISTRICT AUG 11 2015
By Whom? Hubert Perry, Production Foreman	Date and Hour Jim Amos, August 6, 2015 7:35 PM Mike Bratcher, August 6, 2015 7:37 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	RECEIVED

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
On August 6, 2015 5:04 at the Cotton Draw Unit 89 Truck Driver for Black River Trucking was loading produced water when the connecting high pressure 4" hose blew apart releasing 35bbls onto location. The well was immediately shut in and the next truck in line was Standard Trucking so they started recovering the released produced water immediately.

Describe Area Affected and Cleanup Action Taken.*
The affected area was approximately 80' x 120' x 50' all contained on location with 25bbls produced water recovered. The broken hose will be repaired. And environmental company will be contacted to determine the extent of clean up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 8/11/15	Expiration Date: N/A
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines attached <input type="checkbox"/>	
Date: 8/11/15 Phone: 575.748.1829	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 9/11/15

2RP-3198