

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

DAB1524727150 **229137** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: BKU Central Tank Battery SWD	Facility Type: Facility

Surface Owner: Fee	Mineral Owner: Fee	API No. N/A
--------------------	--------------------	-------------

LOCATION OF RELEASE

Unit Letter J	Section 24	Township 17S	Range 29E	Feet from the N/A	North/South Line N/A	Feet from the N/A	East/West Line N/A	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

32.8197

Latitude N32° 49.180 Longitude W104° 01.569

104.0262

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 20 bbls oil & 580 bbls PW	Volume Recovered: 10 bbls oil & 560 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 8/20/2015 6:30 am	Date and Hour of Discovery: 8/20/2015 6:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Amanda Trujillo	Date and Hour: Fri 8/21/2015 5:15 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused when tanks overflowed due to an alarm failure. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred in within containment then overfilled the containment and impacted the pad and nearby pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 8/14/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: <input type="checkbox"/> Remediation per O.C.D. Rules & Guidelines	
Date: August 2, 2015 Phone: 575-748-6940	SUBMIT REMEDIATION PROPOSAL NO. 1014115	

* Attach Additional Sheets If Necessary

LATER THAN: 10/14/15

2RP-3237