Form 3160-5 FORM APPROVED DEPARTMENT OF THE INTERNAL CONSERVATION UNITED STATES (August 2007) OMB NO. 1004-0135 Expires: July 31, 2010 BUREAU OF LAND MANAGEMENTARTESIA DISTRICT Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS 1 2015 Artesia NMNM29234 6. If Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side. Well Name and No. LOTOS FEDERAL 4 1. Type of Well Oil Well Gas Well Other Name of Operator Contact: CINDY H MURILLO API Well No. CHEVRON USA INCORPORATED E-Mail: CHERRERAMURILLO@CHEVRON.COM 30-015-27593-00-S1 3a. Address 3b. Phone No. (include area code) 10. Field and Pool, or Exploratory 15 SMITH ROAD Ph: 575-263-0431 W SAND DUNES MIDLAND, TX 79705 Fx: 575-263-0445 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, and State Sec 9 T24S R31E NWSE EDDY COUNTY, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize □ Deepen ☐ Production (Start/Resume) ■ Water Shut-Off ☐ Notice of Intent ■ Alter Casing ☐ Fracture Treat □ Reclamation ■ Well Integrity Subsequent Report □ Casing Repair ■ New Construction □ Recomplete □ Other ☐ Final Abandonment Notice ☐ Change Plans □ Plug and Abandon ▼ Temporarily Abandon □ Convert to Injection ☐ Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) CHEVRON USA INC REQUESTS TO TEMPORARY ABANDON THE ABOVE WELL. A COPY OF THE MIT CHART IS ATTACHED WITH THE DAILY ROUTINE WORK DONE TO TA THE LOTOS FEDERAL 4 WELL. A CIBP WAS SET AT 6255'. THIS WELL NEEDS A NEW ROD STRING AND TUBING STRING. REPLACING THE EQUIPMENT NOW AT THE CURRENT OIL PRICES IS UNECONIMICAL. THE EQUIPMENT WILL BE REPLACED WHEN THE OIL PRICES IMPROVE IN THE NEAR **FUTURE** CHEVRON WOULD LIKE TO TAITHIS WELL FOR 1 YEAR. SEE ATTACHED FOR the well must be online CONDITIONS OF APPROVAL or plans to P & A must be submitted. Accepted for rec


Feb 2015

I hereby certify that the foregoing is true and correct.

Electronic Submission #315317 verified by the BLM Well Information System For CHEVRON USA INCORPORATED, sent to the Carlsbad Committed to AFMSS for processing by CHRISTOPHER WALLS on 09/04/2015 (15CQ0446SE)

Name (Printed/Typed) CINDY H MURILLO Title PERMITTING SPECIALIST (Electronic Submission) Signature 09/02/2015 THIS SPACE FOR FEDERAL OR STATE OFFICE USE SEP Approved By Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease BUREAU OF LAND MANAGEMENT which would entitle the applicant to conduct operations thereon. CARLSBAD FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





Wellbore Schematic

ield Name Business Unit LOTOS FEDERAL SAND DUNES WEST LOTOS FEDERAL 004 Mid-Continent Land - Original Hole, 9/2/2015 6:31:36 AM Job Details Job Category Start Date Rig/Unit End Date (ftKB) Vertical schematic (actual) Well Services 5/6/2015 4/21/2015 Casing Strings Set Depth (MD) (ftKB) OD (in) WVLen (lb/fl) Grade Top Thread Surface 13 3/8 48.00 H-40 ST&C 599 Intermediate 8 5/8 32.00 J-55 ST&C 4,335 Casing Joints; 17-598; 581.00; 13 3/8; 12.715; 1-1 Production 5 1/2 17.00 J-55 LT&C 8,257 Float Shoe; 598-599; 1.00; 13 3/8; 1-**Tubing Strings** Tubing - Production set at 7,168.5ftKB on 6/8/2010 00:00 Casing Joints; 17-4,334; 4,317.00; 8 Set Depth (MD) (ftKB) 5/8, 7.921, 2-1 String Length (ft) 200 1 **Tubing - Production** Casing Joints: 17-6,497; 6,480.00; 5 1/2; 4.892; 3-1 7,151.52 6/8/2010 7,168.5 OD (in) Wt (lb/ft) Btm (ftKB) . Item Des Grade Jts . Len (ft) Tubing; 17-6,816; 6,799.38; 2 7/8; 2-Tubing 6,799.38 2 7/8 6,816.4 Anchor/catcher 2 7/8 6,819.4 Tubing 27/8 284.99 7,104.4 4,334 9 Seat Nipple 7.105.4 1.00 2 7/8 Float Shoe; 4,334-4,335; 1.00; 8 5/8; Perf Sub 2 7/8 4.00 7,109.4 <3350 Mud Anchor 2 7/8 58.15 7,167.5 **Bull Plug** 27/8 1.00 7.168.5 6,305 Perf; 6,305-6,317; 10/19/1995 **Rod Strings** 6 316 0 Rod Conventional on 6/8/2010 00:00 String Length (ft) G,427 0 Rod - Conventional 6/8/2010 7,104.50 7,105.4 DV Tool; 6,497-6,500; 3.00; 5 1/2; 3-Jts OD (in) Wt ((b/tt) Grade 8tm (fKB) 6,500 0 Polished Rod 1 1/2 26.00 26.9 Fiberglass Sucker Rod 81 3.037.50 3.064.4 6,589 2 Sucker Rod 118 7/8 3,525.00 6.589.4 Sinker Bar 20 1 1/2 6.01 500.00 7,089.4 6.816.3 Anchor/catcher; 6,816-6,819; 3.00; 2 Rod Pump 1 1/2 16.00 7,105.4 6 819 2 Perforations Tubing; 6,819-7,104; 284.99; 2 7/8; 2 7,0229 Entered Shot Total Top (ftKB) Btm (ftKB) (shots/ft) Zone & Completio Perf; 7,030-7,086; 7/11/2003 10/19/1995 6,305.0 6,317.0 18 2.0 7/11/2003 7,030.0 7,086.0 1.0 56 6/16/1994 7 090 7,936.0 7,946.0 3.0 12/7/1993 8.003.0 8.138.0 20 Other Strings Seat Nipple, 7,104-7,105; 1,00; 2 Run Date Pull Date Set Depth (ftKB) Com Perf Sub; 7,105-7,109; 4.00; 2 7/8; 2-Other In Hole 7,1093 Mud Anchor; 7,109-7,168; 58.15; 2 Des Top (RKB): Btm (ftKB) Run Date Pull Date Com Cemented Bridge 7/8: 2-6 7,890.0 7,927.0 7/11/2003 7.1G7 2 Bull Plug; 7,168-7,169; 1.00; 2 7/8; 2-Plug Casing Joints; 6,500-8,256; 1,756,00; 5 1/2; 4.892; 3-3 1,090.1 7,926 8 7.800 0 Perf: 7.936-7.946: 6/16/1994 7.945 4 Perf; 8,003-8,138; 12/7/1993 0.000 6 Float Shoe; 8,256-8,257; 1.00; 5 1/2; 6.250 H Page 1/1 Report Printed: 9/2/2015

Chevron Routine Well Work Daily Job Summary

DATE

5/6/2015

| | AREA | | FIELD NAME | CHEVNO NUMBER | LEASE NAME | API NUMBEI | R |
|---|-----------|--|---|---|---|----------------|-------------------|
| | | DELAWARE BASIN | HOBBS | | LOTOSF4 | . 3 | 300152759300 |
| | Date | | Remarks | | | | Daily Ma Hours |
| | 4/21/2015 | DAY 1 WRITE AND REVIEW JSA'S, TGSM, SPOT IN RIG. ISSUE RU PTW A BREAK MID ROD WITH SEVERE FRAYING. CONTACT PLANNER, ADVISE TO NUBOP, POOH WITH TBG TO ROD PART, UNSEAT PUMP AND POOH WITH | O POOH WITH TBG SCANNING, CH. | ANGE OVER TOOLS, PREP | • | | 4 |
| | 4/22/2015 | DAY 2 WRITE AND REVIEW JSA'S, TGSM, ATTEMPT TO NUBOP AND BR SWAP OUT RIG TO PREVENT US FROM HAVING THE BRAKES LOCK UP W INSPECT REPLACEMENT RIG AT MABORS YARD, ADDRESS ANY REPAIRS | VITH NO WAY TO ISSOLATE THE WE | | | | 0 1 |
| | | DAY 3-WRITE AND REVIEW JSA'S AND TENENT #8, RIGGED PASSED FINA TOOLS, WSM ON LOC WHILE FUNCTION TESTING BOP, BLED DWN CSNO FG ROD SECURED WELL AND EQUIPMENT SION, PROJ OPS: UNSEAT PU | G. PUMPED 20 BBW TO KILL CASING | NOWH, UNSET TAC, 16 PN | TS OF TENSION, NUBOP, POOH TO ROD | | N 1 5 |
| | 4/29/2015 | DAY 4- CREW ATTENDED RCA IN HOBBS NABORS YARD, PROJ OPS: POC | OH TO PART UNSEAT PUMP POOH V | v/RODS | | | 9 |
| | 4/30/2015 | DAY 5-WRITE AND REVIEW JSA'S AND TENENT#10, BLED DWN WELL PUR CONTACTED PLANNER ABOUT LD ALL FG RODS, LD FG RODS AND POOR EQUIPMENT SION, PROJ OPS; RU SCANNERS POOH WITBG WHILE SCAN | H WISTEEL ROOS . LO SINKER BARS | | | | 9 |
| • | 5/1/2015 | DAY 6-WRITE AND REVIEW JSA'S AND TENENT #1, PREPARED TOOLS CA PULLED 44 JOINTS AND TBG STARTED TO COME OUT GREEN AND RED I WYYELLOW BAND TBG, RD SCANNERS LD DOWN REMAINDER OF TBG PO SECURED WELL SIOW, PROJ OPS: RECIEVED ORDERS FROM PLANNER | DUE TO EXTERNAL AND INTERNAK JILLED 42 GOOD JOINTS 23 YELLOV | PITTING, AND ROD WEAR, 1, 19 Blue, 84 Green, and | CONTACTED PLANNER AND WILL BE LD T 20 RED AND LD REST OF TBG AND LD BH | 6G AND REPLACI | ING 8 |
| | 5/4/2015 | DAY 7-TG SAFETY MEETING REVIEW USA'S AND TENTENT #4, POOH WIKE AT 6255' POOH WAVIRELINE, MADE 1 MORE RUN DUMPED 50' OF CEMEN EQUIPMENT SION, PROJ OPS FIN PU TBG RIH WIRODS LD ROD CIRC PA | T, POOH RD WIRELINE, PU BP AND | PERF SUB RIH WITBG AND | | • | 5P 12 |
| | 5/5/2015 | DAY 8 TGSM REVIEW JSA'S TENENT 5 FINISH PICKING UP TBG CO TOOL STRING ND BOP NUWH SDON PROJ OPS CHART TEST CSG FOR NIM OCI | ,* | | E TEST CSG TO 540# FOR 40 MIN GOOD I | POOH LD WORK | 12 |
| | 5/6/2015 | DAY9 TGSM REVIEW, JSA'S AND TENENT #6, RU PUMP TRUCK PERFORMS RU PUMP TRUCK, ISSUED PTW ROSU NOTIFIED DSC OF RD, CLEANED LG | | E LEAKING RETESTED AT 9 | 86# FOR 35 MINUTES LOST 5# BLM WAS (| 300D WITH TEST | T. 7 |

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 6 months ending 3/4/2016 subject to conditions of approval. Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Lotos Federal #4

- 1. Well is approved to be TA/SI for a period of 6 months or until 3/4/2016
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 3/4/2016
- 4. COA's met at this time.