

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526127389

303900

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Memorial Production Operating LLC	Contact	Heather Dolphin
Address	500 Dallas Street Houston TX 77002	Telephone No.	832-797-1334
Facility Name	North Square Lake Unit (closest well #69)	Facility Type	Well
Surface Owner	Mineral Owner	BLM	API No. 30-015-03925

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	25	16S	30E					Eddy

Latitude 32°53'13.24"N Longitude 103°55'22.20"W

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	20bbls	Volume Recovered	0bbls
Source of Release	Injection Line	Date and Hour of Occurrence	9/13/15	Date and Hour of Discovery	2pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Heather Patterson, OCD / Art Arias, BLM		
By Whom?	Heather Dolphin	Date and Hour	09/14/2015 2pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 14 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.\*

n/a

Describe Cause of Problem and Remedial Action Taken.\*

Underground injection line developed hole between NSLU #51 & NSLU #69. Line was dug up and repaired.

Describe Area Affected and Cleanup Action Taken.\*

Off location (along side lease road and into pasture)

40ft. x 2ft with a 12' puddle - unrecoverable

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 

Printed Name: Heather Dolphin

Title: Sr. Regulatory Specialist

E-mail Address: heather.dolphin@memorialrd.com

Date: 9/14/15

Phone: 832-797-1334

Approved by Environmental Specialist: 

Approval Date: 9/18/15

Expiration Date: N/A

Conditions of Approval:

Attached ☐

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 10/22/15

2RP-326

\* Attach Additional Sheets If Necessary