

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526142024

303900

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Memorial Production Operating LLC	Contact	Heather Dolphin
Address	500 Dallas Street Houston TX 77002	Telephone No.	832-797-1334
Facility Name	North Square Lake Unit #100	Facility Type	Well

Surface Owner	Mineral Owner	BLM	API No.	30-015-10752
---------------	---------------	-----	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	31	16S	31E					Eddy

Latitude 32°53'6.83"N Longitude 103°54'32.98"W

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	10bbls	Volume Recovered	0bbls
Source of Release	Well	Date and Hour of Occurrence	9/14/15	Date and Hour of Discovery	2pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Heather Patterson, OCD / Art Arias, BLM		
By Whom?	Heather Dolphin	Date and Hour	09/14/2015 5pm	NM OIL CONSERVATION	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.*	SEP 14 2015
n/a	RECEIVED

Describe Cause of Problem and Remedial Action Taken.*



The main valve on the NSLU #100 injection well developed a leak, could not SI well due to broken valve, re-routed water to Frac tank and replaced valve.

Describe Area Affected and Cleanup Action Taken.*

Off location (pasture)

30ft. x 1ft with a 40' circle spray - unrecoverable

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Heather Dolphin	Approved by Environmental Specialist: 	
Title: Sr. Regulatory Specialist	Approval Date: 9/18/15	Expiration Date: N/A
E-mail Address: heather.dolphin@memorialrd.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/14/15 Phone: 832-797-1334	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/22/15

2RP-3264