

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 16 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

nab1526429388

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. <i>16694</i>	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Neff Federal #1 and #3 SWD Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No. 30-015-28281

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	25	22S	31E					Eddy County, NM

Latitude N 32.36758° Longitude W 103.73418°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	Unknown, mixed with rain water	Volume Recovered	80 bbls, mostly rain water
Source of Release	Corrosion of a 4" discharge line	Date and Hour of Occurrence	08/24/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson, NMOCD and Shelly Tucker, BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	08/25/2015 @ 3:06 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

~~If a Watercourse was Impacted, Describe Fully.~~


Describe Cause of Problem and Remedial Action Taken.*

Corrosion of a 4" steel discharge line caused an unknown amount of produced water to leak onto the ground. The line was repaired and a vacuum truck recovered 80 bbls of fluids, mostly rain water.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 80' x 75' just west of the lined battery. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				OIL CONSERVATION DIVISION	
Printed Name:	Chancey Summers			Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title:	HES Lead			Approval Date:	9/21/15
E-mail Address:	Chancey.Summers@oxy.com			Expiration Date:	N/A
Date:	9-11-15			Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	(432) 685-5824			Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: *10/22/15*

2RP-3268